

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: KALKASKA (County)	Located In	Corner Code #
1. Public Land Survey	T 25N R 7W D-12	
2. Property Controlling in Section	S T R	
3. Miscellaneous Property in Section	S 32 T 25N R 7W 5	
4. Lot No:	Recorded Plat:	
5. Private Claims:		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Craig W. McVean, in a field survey on June 28, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- D-12 – DNR Cor. Rec. –1972  
C. Roser - Set 1" x 36" Pipe with Cedar Post & Loc. Tag.  
N12°E 54.8' to 6" Maple, N67°W 34.5' to 9" Twin Maple  
S73°W 53.6' to 10" Triple Maple.  
- Cer. Sur. - E. Farrier – 1981 - Farrier Surveying #0481  
Fd. ¾" pipe wits. recorded in lib.1, Pg. 72
- 5- DNR Cor. Record - 1" X 36" pipe was set by C. Roser – 1972 along with a cedar post containing a location tag  
N58°W 55.5' to a 3" Cherry, S44°W 24.3' to a 4" Cherry  
S24°E 39.2' to a 4" Cherry  
- Rec. Sur. L.3 Pg. 291 - J.L. Wilcox – 1989  
DNR wit's. used.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

- D-12 – Ctr. ¼ Iron Sec. 32  
Fnd. 1" pipe .5' S & E of Cedar Post with Loc. Tag.  
per DNR record. Roser's 1" Iron Pipe accepted as the best available evidence of the position of the corner.
- 5- Center North 1/16 Corner of Section 32-Found 1" iron pipe .9' SW of cedar post with location tag. Roser's 1" Iron pipe accepted as the best available evidence of the position at the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- D-12 – 1" pipe  
N62°W 35.13' to set N&T in N. side of triple 13" R. Maple(CFR)  
N20°E 55.06' to set N&T in E. side of 11" R. Maple(CFR)  
S82°E 45.45' to set N&T in S. side of 4" Fir  
S2°W 18.0' to set N&T in W. side of 5" Fir  
Set Blue Carsonite Post 1' SE
- 5- 1" Pipe  
Set blue Carsonite post with location tag 1' to NE.  
N58°W 55.66' to set N&T in S. side of 9" Cherry (CFR)  
S40°W 24.62' to set N&T in E. side of 6" Cherry (CFR)  
S26°E 39.31' to set N&T in W. side of 6" Cherry (CFR)  
N45°E 32.09' to set N&T in NW side of 6" Cherry

Signed by: Craig W. McVean  
Surveyor's Michigan License No.: 39088

Date: 8/31/2000

