

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Kalkaska
(County)

Located In

Corner Code #

1. Public Land Survey T 26N R 5W I4
T R
2. Property Controlling in Section S T R
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on July 31, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I4 – ¼ corner common to sections 10 & 11, T26N, R5W

- 1852 – GLO Resurvey – G. Cannon – Set quarter section post 10 & 11. –
1) Beech 11" N85°W 26, 2) W. Pine 12" S75°E 16.
- 1911 – County Survey Record Section 11 – No corner description.
- 1913 – Fargo Engineering – Found remains of two U.S. witnesses. Set 1" iron pipe and crockery.
– 3) SP. Pine 7" S72½°E 0.27½, 4) W. Pine stp. 6" N7°W 0.18¾.
- 1978 – Consumer's Power Co. Survey drawing #S-F17406 – D. Ankrom, PS #21265 – Found ¾" pipe & crockery.
– 4) scribed W. Pine stump N7°W 12.4', 5) 4" R. Pine N80°E 1.45', 6) 21" Poplar S80°E 17.35'.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I4 – ¼ corner common to sections 10 & 11, T26N, R5W

Found hooked end Fargo pipe with butter dish below. No GLO evidence was found. Accepted found Fargo pipe as a **careful and faithful perpetuation of the position of the original corner**, and replaced it with a stamped 4" DNR aluminum cap on a 1" X 36" long galvanized iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I4 – 4" stamped aluminum cap on 1" X 36" long galvanized iron pipe – Set Blue post 1' Northwest.

N46°E 38.75' to set nail & tag in NW. side 5" W. Pine
S52°W 5.04' to set nail & tag in SE. side 7" R. Pine
N74°W 71.74' to set nail & tag in S. side 11" R. Pine
N20°W 63.71' to set nail & tag in W. side 4" R. Maple



Signed by:

Joshua R. Davidson

Date:

DEC. 16, 2014

Surveyor's Michigan License No.:

46659