

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970.

For Corners In: Kalkaska Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_  
(County)

1. Public Land Survey T 26N R 5W I6  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous Property in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Joshua R. Davidson, in a field survey on October 7, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

**I6 – ¼ corner common to sections 14 & 15, T26N, R5W**

– **1852** – GLO Resurvey – G. Cannon – Set quarter section post 10 & 11. –

1) Y. Pine 18" S81°E 13, 2) Y. Pine 20" N87°W 54.

– **1957** – DNR corner record – B. Buckler, PS #8887 – This corner was found by forestry division survey crew while making a partial resurvey of this township. Found a 1¼" pipe at corner, with sites of possible government BTs in place. Corner was obviously used in the location of, or set in relation to, the section corners North and South. – 1" pipe with 4" Brass cap – 3) 7" J. Pine N82°E 75 links, 4) 9" J. Pine S10°E 98 links.

– **1978** – Consumer's Power Co. Survey drawing #S-F17406 – D. Ankrom, PS #21265 – found 1" pipe with 4" brass cap. – 3) 7" J. Pine N82°E 75 links, 4) 9" J. Pine S10°E 98 links.

– **1980** – Certificate of Survey – N. F. Parker, PS #16939 – Found MDNR cor.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**I6 – ¼ corner common to sections 14 & 15, T26N, R5W**

Found 4" Department of Conservation (DOC) brass cap on 1" iron pipe with 1¼" pipe alongside. Found Pine stump S80°E 8.6' to face believed to be GLO witness (#1). Accepted found 4" DOC monument as the **best available evidence of the position of the original corner.**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**I6 – 4" Department of Conservation brass cap on 1" iron pipe – found blue post 1' East**

N82°E 51.04' to set nail & tag in S. side 6" W. Pine  
S36°E 34.43' to set nail & tag in SW. side 8" W. Pine scribed 'XBT'  
S45°W 38.47' to set nail & tag in SE. side 10" W. Pine scribed 'XBT'  
N55°W 63.68' to set nail & tag in SW. side 9" J. Pine

Signed by:

Joshua R. Davidson

Date:

DEC. 16, 2014

Surveyor's Michigan License No.:

46659

