

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Kalkaska  
(County)

Located In

Corner Code #

1. Public Land Survey T 26N R 5W K4  
T R  
2. Property Controlling in Section S T R  
S T R  
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on October 7, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

**K4 – ¼ corner common to sections 11 & 12, T26N, R5W**

- 1852 – GLO resurvey – G. Cannon – Set quarter section post – 1) SP. Pine 14" N82°E 31, 2) SP. Pine 4" S78°W 22
- 1911 – County Survey Record Section 11 – No corner description.
- 1957 – DNR corner record – B. Buckler, PS #8887 – This corner was established by proportionate measurement between DeLamater's section corner North and original section corner South by Forestry Division survey crew while making a survey in this area. – 1" pipe with 4" brass cap – 3) 8" J. Pine N59°W 48½ links, 4) 10" J. Pine N44°E 38½ links.
- 1978 – Consumer's Power Co. Survey drawing #S-F17406 – D. Ankrom, PS #21265 – Found 4" cap on 1" pipe. – 3) 8" J. Pine N59°W 32.01', 4) 10" J. Pine N44°E 25.41'.
- 1987 – DNR Survey Map plan no. R-40-BD. – C. Roser, PS #12028 – Found Dept. Mon. as set in 1957 Dept. Survey. – 4) 14" J. Pine N47°E 25.4', 5) 2" J. Pine N23°W 19.4', 6) 6" J. Pine S25°E 5.4', 7) 7" J. Pine S70°W 4.9', Ctr. gas line West 82±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**K4 – ¼ corner common to sections 11 & 12, T26N, R5W**

Found 4" Department of Conservation (DOC) brass cap on 1" pipe in good condition. Found witnesses #4, #6 & #7 in good condition and found stump of witness #5 fitting position. No GLO evidence was found. Distance South to 'K5' measures 2665.01'-grid (2640'-GLO), distance North to K3 measures 2663.66'-grid (2640'-GLO). **Accepted found 4"**  
**DOC Monument as a careful and faithful reestablishment of the position of the original corner.**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**K4 – 4" Department of Conservation brass cap on 1" pipe. – Cedar post 1.4' Northeast.**

N48°E 25.97' to set nail & tag in SE. side 16" J. Pine (#4)  
S25°E 5.64' to set nail & tag in SW. side 8" J. Pine (#6)  
S66°W 5.15' to set nail & tag in NW. side 8" J. Pine (#7)  
N02°W 39.70' to set nail & tag in E. side 5" J. Pine

Signed by:

*Joshua R. Davidson*

Date:

DEC. 16, 2014

Surveyor's Michigan License No.:

46659

