



8 0 4 1 5 3 2

Tx:4028993

2/11/2015 4:45:00 PM

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska  
(County)

Located In

Corner Code #

1. Public Land Survey	T	_____	R	_____	_____
	T	_____	R	_____	_____
2. Property Controlling in Section	S	15	T	26N	R 5W 2, 9
	S	_____	T	_____	_____
3. Miscellaneous Property in Section	S	_____	T	_____	_____
	S	_____	T	_____	_____

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Joshua R. Davidson, in a field survey on April 22, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

2 – E 1/16 corner common to sections 10 & 15

1978 – Consumers Power Company Survey Map – Drawing No. S-F17406, sheet 4 – Duane A. Ankrom, PS #21265 – ½" rebar set with C.P. Co. Cap.

9 – CE 1/16 corner section 15

1980 – Certificate of Survey – L. 2, P. 600 – Norman Parker, PS #16939 – Found corner of record.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

2 – E 1/16 corner common to sections 10 & 15

Set 2" aluminum cap on 5/8" X 34" rebar per standard BLM procedure. N16°W 2.73' to found 4" square concrete monument not utilized in this survey. Did not find Consumers Power Company corner. The set 2" aluminum cap on 5/8" X 34" rebar is accepted as the best available evidence of the position of the corner.

9 – CE 1/16 corner section 15

Found a ½" rebar. Also found a 4" square concrete monument N50°E 2.97'. Accepted found ½" rebar as the best available evidence of the position of the corner and replaced it with a 2" aluminum cap on 5/8" x 34" rebar.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2 – A stamped 2" aluminum cap on 5/8" x 34" rebar.

N47°E 32.21' to set nail & tag in SE. side 13" R. Pine  
East 28.84' to set nail & tag in N. side 9" W. Pine  
South 56.64' to set nail & tag in W. side 6" W. Pine  
N16°W 2.73' to 4" square concrete monument  
Set blue post with location tag 1' East

9 – A stamped 2" aluminum cap on 5/8" X 34" rebar.

N50°E 2.97' to 4" square concrete monument  
N78°E 12.33' to set nail & tag in SW. side 13" J. Pine  
S38°E 29.00' to set nail & tag in SW. side 14" J. Pine  
S57°W 26.52' to set nail & tag in NW. side 7" J. Pine  
N42°W 15.64' to set nail & tag in SW. side 4" R. Pine  
Set blue post with location tag 1' Southeast

Signed by:

Surveyor's Michigan License No.:

46659

Date:

2-11-2015

