



8 0 4 1 5 3 1

Tx:4028993

2/11/2015 4:45:00 PM

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska  
(County)

Located In

Corner Code #

1. Public Land Survey	T	_____	R	_____	_____
	T	_____	R	_____	_____
2. Property Controlling in Section	S	15	T	26N	R 5W 8, 11
	S	_____	T	_____	_____
3. Miscellaneous Property in Section	S	_____	T	_____	_____
	S	_____	T	_____	_____

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Joshua R. Davidson, in a field survey on July 10, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8 – CW 1/16 corner section 15

1978 – Consumers Power Company Survey Map – Drawing  
No. S-F17406, sheet 5 – Duane A. Ankrom, PS #21265  
– 1/2" rebar set with C.P. Co. Cap.

11 – SW 1/16 corner section 15

1978 – Consumers Power Company Survey Map – Drawing  
No. S-F17406, sheet 5 – Duane A. Ankrom, PS #21265  
– 1/2" rebar set with C.P. Co. Cap.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8 – CW 1/16 corner section 15

Found a 1/2" X 24" rebar & Consumers Power Company cap.  
Found a 4" square concrete monument 2.33' North. Accepted  
found 1/2" X 24" rebar and cap as the best available evidence of  
the position of the corner and replaced it with a 2" aluminum  
cap on 5/8" x 34" rebar.

11 – SW 1/16 corner section 15

Found 1/2" X 24" rebar with broken cap. Replaced it with a  
2" aluminum cap on a 5/8" X 34" rebar and is accepted as  
the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 – A stamped 2" aluminum cap on 5/8" x 34" rebar.

North 2.33' to 4" square concrete monument  
S45°E 2.10' to set nail & tag in SW. side 7" R. Pine  
S43°W 15.94' to set nail & tag in SE. side 8" W. Pine  
N81°W 26.43' to set nail & tag in N. side 8" W. Pine  
Set blue post with location tag 1' Northeast

11 – A stamped 2" aluminum cap on 5/8" X 34" rebar.

N23°E 8.81' to set nail & tag in SE. side 6" W. Pine  
S77°E 23.05' to set nail & tag in N. side 6" W. Pine  
S07°E 13.23' to set nail & tag in W. side 10" Oak  
S46°W 13.45' to set nail & tag in SE. side 6" W. Pine  
Set blue post with location tag 1' Southeast

Signed by:

Surveyor's Michigan License No.:

46659

Date:

2-11-2015

