

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Kalkaska (County) Located In Corner Code #
1. Public Land Survey T 26N R 5W G8
2. Property Controlling in Section S T R
3. Miscellaneous Property in Section S T R
4. Lot No: Recorded Plat:
5. Private Claims:

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 in a grid pattern, with a dot in cell G22.

I, Craig W. McVean, in a field survey on October 13, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G8 - 1852 - GLO - G. Cannon - Set qr. Sec. post, 1) Hemlock 12" N1°E 37, 2) Balsam 7" S25°W 25
- 1957 - DNR corner record - B. D. Buckler, PS #8887 - This corner was found by forestry division survey crew while making a survey in this area. Found a 1/2" X 24" iron bar in corner set by G. F. Delamater in 1946, as shown by his tags in the witnesses. Accepted as 1/4 corner in this survey. - set 1" pipe with 4" brass cap, 3) Old NBT 16" W. Pine S82°W 24 L., 4) Old NBT 22" W. Pine N10°W 63 L., 5) 8" W. Birch S3°W 4 L.
- 1978 - Consumer's Power Co. Survey drawing #S-F17406, sheet 6 - Duane A. Ankrom, P.S. #21265 - Found DNR Mon. 4" cap & 3/8" rebar, 3) 16" W. Pine S82°W 15.84', 4) 22" W. Pine N10°W 41.58', 5) 8" W. Birch S3°W 2.64'.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G8 - 1/4 Corner common to sections 21 & 22, T26N, R5W - Found 4" Department of Conservation Brass Cap Monument on 1" iron pipe with 1/2" rebar alongside. Found witnesses #3 & #4 in good condition and found stump remains of witnesses #5. No GLO evidence found. Monument is 3'± East of bottom of bank in cedar swamp. Measured North 32' to bottom of bank & 63' to top of bank, West 28' to top of bank and South 18' to bottom of bank & 65' to top of bank. Measured South 391' to South bank of stream course SW compares to GLO (6.15 CH.) 405.9'. 4" DOC Monument accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G8 - 4" DOC Brass Cap on 1" iron pipe. Place broken concrete around monument. Set Blue carsonite Post 1' East.
N40°E 43.19' to set nail & tag in NW side 12" Tamarack scribed 'XBT'
N82°E 41.36' to set nail & tag in S side 10" Cedar scribed 'XBT'
S48°E 49.12' to set nail & tag in SW side 12" Tamarack scribed 'XBT'
S84°W 16.58' to found nail in NW side 40" W. Pine (#3)
N08°W 42.08' to found nail in E side 40" W. Pine (#4)



Signed by: [Signature]
Surveyor's Michigan License No.: 39088

Date: 1/20/2011