



8 0 2 3 2 8 0

TX:4016447

11/29/2012 1:00:00 PM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska

(County)

Located In

Corner Code #

1. Public Land Survey

T _____ R _____
T _____ R _____2. Property Controlling
in SectionS 20 T 26N R 6W 8
S 20 T 26N R 6W 113. Miscellaneous
Property in SectionS _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____

Recorded Plat: _____

5. Private Claims: _____

I, Joshua R. Davidson, in a field survey on April 4, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8 - 1919 - CSR - W.S. Merrill, Bk. 20, P. 88,
Balsam 8 North 15
Balsam 8 N55W 28.

11 - none



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8 - CW 1/16 corner section 20. Dug a 4' X 6' area in search of Merrill corner. No evidence of his corner or witnesses. Set stamped 2" Aluminum cap on 5/8" x 60" rebar per BLM standard procedure, in line with old fence remains to North.

11 - SW 1/16 corner Section 20. Set stamped 2" aluminum cap on 5/8" X 34" rebar per BLM standard procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 - Set a stamped 2" Aluminum Cap on 5/8" x 60" rebar

N30°E 22.06' to set nail & tag in SE. side 10" Cedar
S65°E 25.58' to set nail & tag in SW. side 5" Cedar
S05°W 10.27' to set nail & tag in W. side 2" Red Maple
S87°W 23.20' to set nail & tag in S. side 10" Cedar
Set blue Carsonite post with location tag 1' Northwest

11 - Set a stamped 2" Aluminum Cap on 5/8" X 34" rebar.

N80°E 47.80' to set nail & tag in S. side 6" Red Maple
S08°W 16.32' to set nail & tag in E. side 5" Cedar
S60°W 26.50' to set nail & tag in NW. side 10" Cedar
N24°W 53.66' to set nail & tag in W. side 3" Red Maple
Set blue Carsonite post with location tag 1' Southwest

Signed by:

Date:

11-29-2012

Surveyor's Michigan License No.:

46659