

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 26 NR. 6 W. --
T. 27 NR. 6 W

Kalkaska COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 3-4-33-34

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

9" Cedar	-	N16W	-	28 links
6" Cedar	-	S30E	-	52 links
8" Balsam	-	S50W	-	27 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Found an old squared stake at corner with Hemlock stumps in place NE, SE, and a possible site SW for probable government BTs. When digging, found definite evidence of old stake bottom which is considerably older than that visible on surface. Checks with swamp edge east. Although this point falls almost 2 rods south of a straight town line, it was thought that the probable government evidence, and previous work which was done when better evidence was available, would provide sufficient cause to accept the corner as found and described. This corner was obviously used to restore the 1/4 corner north, since the 1/4 corner falls almost exactly at midpoint on line.

Corner was placed and witnessed ;8-13-57.

SURVEYORS SEAL

SIGNED

REGISTERED LAND SURVEYOR

DATE 10/20/59