

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 26 NR 6 W

Kalkaska COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 15 and 22

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

6" Balsam - N44E - 32 links

6" Cedar - N25W - 47 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established by Forestry Division survey crew while completing a partial resurvey of this township. Set corner by proportionate measurement - midpoint, on line- between section corners. Original evidence destroyed in road construction. Falls about 15 links north of apparent centerline of E-W Co. road.

Corner was placed and witnessed September 24, 1959.

SURVEYORS SEAL

SIGNED

Kenneth J. Ostling
REGISTERED LAND SURVEYOR

DATE 9/25/59