

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

**SURVEY &
REMONUMENTATION**

FEB 26 2001

SECTION

Register of Deeds Stamp & File Number

For corners in

KALKASKA Located in: Corner Code #
(County)
2000 REMONUMENTATION
1. Public Land Survey T 27N R 6W H-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, EUGENE FARRIER, in a field survey on September 7, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

H-7: 1/4 Corner Common to Sections 15 and 22, T27N-R6W
1852: GLO resurvey by G.H. Cannon; set post for corner; Sugar 8", N 60°E, 14 links; Sugar 6", S 60°W, 44 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-7: 1/4 Corner Common to Sections 15 and 22, T27N-R6W
Set 5/8" rebar with brass cap M.P.O.L. between found section corners.
No GLO witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-7: 1/4 Corner Common to Sections 15 and 22, T27N-R6W
Set 5/8" rebar with brass cap M.P.O.L. between found section corners. Corner is 2' South of E-W road and on old fence North.
N 52°E, 90.28', 10" Red Pine, set nail and tag
N 82°E, 102.34', 34" Maple, set nail and tag
S 66°E, 73.61', 24" Maple, set nail and tag
S 39°W, 52.45', 8" Triple Cherry, set nail and tag

Kalkaska County Peer Group accepted the above monument as a careful and faithful reestablishment of the position of the original corner.

Ratified by Peer Group
P.A. 345-1990 Kalkaska County

Chairman Eugene Farrier

Date 2-14-01



Signed by Eugene Farrier
Surveyor's Michigan License No. 24594

Date 2-15-01



3026844
Page: 1 of 1
02/16/2001 10:28A
REMON
LB: 6 PG: 173

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 25, 1971
REVISED MAY 14, 1975
REVISED JAN, 1993
REVISED OCT., 1995