



8 0 5 0 0 1 1

Tx:4034718

2/3/2016 4:05:00 PM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska

(County)

Located In

Corner Code #

1. Public Land Survey	T		R		
	T		R		
2. Property Controlling in Section	S 8	T 27N	R 7W		11, 12
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on October 8, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

DOCUMENT # 3128799

STATE OF MICHIGAN

KALKASKA COUNTY

RECORDED: 03/03/2016 4:13 PM

PAGES: 1

RECORDING FEES: 14.00

JOANN DEGRAAF REGISTER OF DEEDS

BK: 4 PG: 7

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

11 – SW 1/16 corner section 8

– None

12 – CS 1/16 corner section 81979 – Certificate of Survey – Liber 2, Page 368 –
James Fletcher, PS #19830 – set iron.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

11 – SW 1/16 corner section 8

Set 2" aluminum cap on 5/8" X 34" rebar per standard BLM procedure.

12 – CS 1/16 corner section 8

Found 1/2" X 24" rebar and broken cap. Replaced it with a 2" aluminum cap on 5/8" X 34" rebar.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

11 – A stamped 2" aluminum cap on 5/8" x 34" rebar.East 44.98' to set nail & tag in N. side 7" W. Pine
S38°E 56.58' to set nail & tag in NE. side 16" W. Pine
S62°W 11.20' to set nail & tag in N. side 8" W. Pine
N07°W 7.62' to set nail & tag in W. side 12" Oak
Set blue post with location tag 1' Southeast12 – A stamped 2" aluminum cap on 5/8" x 34" rebarN20°E 49.81' to set nail & tag in W. side P. Pole
S60°E 47.67' to set nail & tag in NE. side 10" R. Pine
S42°W 86.00' to set nail & tag in NW. side 17" R. Pine
N89°W 49.97' to found 1/2" rebar & cap #20706, #24600

Signed by:

Surveyor's Michigan License No.:

46659

Date:

March 3, 2016

