

SURVEY & REMONUMENTATION

FEB 18 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

KALKASKA COUNTY, MICHIGAN
RECEIVED

For corners in

KALKASKA

Located In:

Corner Code #

1993 DEC 22 PM 1:28

Joan Hall
REG. OF DEEDS

Register of Deeds Stamp & File Number

1993 REMONUMENTATION

- | | | | | | |
|------------------------------------|---|-----|---|----|------|
| 1. Public Land Survey | T | 27N | R | 7W | A-11 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous Property in Sec. | S | | T | R | |
| | S | | T | R | |

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, EUGENE FARRIER, in a field survey on DEC. 2, 19 93, do hereby certify that under requirements of P.A. 1, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, re-established, monumented, re-monumented, recovered, found as expressed by: ow:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-11 cor. common to Sec. 30 & 31, T27N-R7W & Sec. 25 & 36, T27N-R8W
1850 GLO re-survey: set Cedar Post Cedar 9", S60W, 13; Cedar 8", N3W, 21;
Cedar 10", S83E, 16; Cedar 12, N46E, 34.
12-72, N.F. Parker, surv. for Northern Mich. Gas, dwg # S-G 17506. Found
old Cedar Stake & 1 1/2" Iron Pipe. Wit. 8" Cedar S39N, 7.9'; 10" Spruce
S65E, 19.8'.
1973, J.L. Wilcox, surv. of Sec. 19, found 1" pipe w/cap #16939. Wit.
N15W, 20.80', 6" Balsam; S60E, 19.98', 10" Tamarck; S40W, 8.32', 10"
Cedar; set 4"x4" Sq. Cedar Post.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11 cor. common to Sec. 30 & 31, T27N-R7W & Sec. 25 & 36, T27N-R8W
Found and accepted 3/4" Iron Pipe 0.8' above ground, fd accessories. Cor.
sits on W'ly edge of a 6' wide N-S trail & 23' S. of E-W brush line.
On 12-16-93 the Kalkaska Co. peer group approved the above monument as a
careful and faithful reestablishment of the position of the original
corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11 cor. common to Sec. 30 & 31, T27N-R7W & Sec. 25 & 36, T27N-R8W
Found 3/4" Iron Pipe - Set 5/8"x36" re-bar w/ Aluminum Cap in center of
pipe. Did not find any outstanding GLO witnesses.
N22W, 25.03', 8" Cedar, (fd nail & washer).
N30E, 31.56', 12" Doug. Fir, (set spk.).
N54E, 27.82', 12" Dead Cedar, (fd nail & washer).
S40W, 7.91', 10" Cedar, (fd. spk.).
S65E, 19.8', 14" Doug. Fir, (fd. spk.).

Signed by Eugene Farrier

Date 12-22-93

Surveyor's Michigan License No. 24594

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19
REVISED MAY 14, 19
REVISED JAN., 19