

FEB 18 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>KALKASKA</u> (County)	Located In:	Corner Code <u>E-7</u>
1993 REMONUMENTATION		
1. Public Land Survey	T <u>27N</u> R <u>7W</u>	<u>E-7</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

KALKASKA COUNTY, MICHIGAN
RECEIVED

1993 DEC 22 PM 1:30

Joan Hall
REG. OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, EUGENE FARRIER, in a field survey on NOV. 22, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-7 cor. common to Sec. 16, 17 20 & 21, T27N-R7W
1850 GLO re-survey; set Birch post; Y. Pine 10" S67E, 22, W. Pine N48W 19.
3-28-19, W.S. Merrill, Co. Surv. visited corner no accessories.
5-1952, A.L. Drago, Co. Surv. fd axle shaft set by State.
10-17-72, J.L. Wilcox, fd Liber 1 Pg 243 of Surv.
10-14-75, J.L. Fletcher, fd 1 1/4" iron bar, Liber 1 Pg 749 of Surv.
12-8-75, LCRC Liber 1, Pg 369.
10-2-79, W.B. Batzer, fd iron marker, Liber 2 Pg 521 of Surv.
2-27-89, E. Farrier, fd axle shaft, Liber 3 Pg 292 of Surv.
3-2-89, LCRC Liber 2 Pg 372.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-7 cor. common to Sec. 16, 17 20 & 21, T27N-R7W
Found and accepted axel shaft in C/L Court St (M-66) & 10' South of C/L Hyde St. GLO witnesses fell in road cut. Pulled axel shaft & reset w/ 5/8"x36" re-rod w/ Brass Cap, 0.6' below bit.
On 12-16-93 the Kalkaska Co. peer group approved the above monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-7 cor. common to Sec. 16, 17 20 & 21, T27N-R7W
Fd. axel shaft, pulled & reset w/ 5/8"x36" re-bar w/ brass cap, 0.6' below Bit. Set Mon. box.
N28E, 39.00', "X" in SW M.H. Rim.
N41E, 56.85', 4" steel post
S67W, 43.48', Guy Post.
S55E, 38.42', P. Pole.

Signed by

Eugene Farrier

Date 12-22-93

Surveyor's Michigan License No.

24594

