

FEB 18 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KALKASKA

(County)

1993 REMONUMENTATION

1. Public Land Survey

T 27N R 7W

Corner Code #

E-9

2. Property Controlling  
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

KALKASKA COUNTY, MICHIGAN  
RECEIVED

1993 DEC 22 PM 1:31

*Joan Hall*  
REG. OF DEEDS

Register of Deeds Stamp & File Number

I, EUGENE FARRIER, in a field survey on NOV. 30, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

F-9 cor. common to Sec. 21 & 28, T27N-R7W  
1850 GLO re-survey: set post, Beech 5", S66W, 25; Beech 5", N70E, 30.  
7-31-07, W.S. Merrill, Co. Sur., visited cor. no accessories.  
12-10-72, G.R. McKelvey, set broken cold chisel, Liber 1 Pg 265 of Surv.  
1-5-73, LCRC Liber 1 Pg 163.  
2-1-74, J.L. Fletcher, fd broken cold chisel, Liber 1 Pg 476 of Surv.  
5-31-74, J.L. Fletcher, fd broken cold chisel, Liber 1 Pg 550 of Surv.  
12-13-76, J.L. Fletcher, fd broken cold chisel, Liber 1 Pg 951 of Surv.  
12-1-76, J.L. Fletcher, fd broken cold chisel, Liber 2 Pg 1 of Surv.  
6-13-79, J.L. Fletcher, fd broken cold chisel, Liber 2 Pg 351 of Surv.  
1973, Survey by Gourdie Farser & Assoc., used cor. no accessories.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-9 cor. common to Sec. 21 & 28, T27N-R7W  
Found and accepted broken cold chisle in C/L M-72, 6.8' West of old (down) fnc line, fd Wilcox wit. from field book 454 pg 26.  
On 12-16-93 the Kalkaska Co. peer group approved the above monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-9 cor. common to Sec. 21 & 28, T27N-R7W  
Found broken cold chisle from accessories, replaced w/ 5/8"x18" re-rod w/ Brass Cap in Mon. Box.  
S42W, 85.48', 19" R. Pine (fd nail w/tag N. fc.)  
S14W, 54.10', 14" R. Pine (fd nail w/tag W. fc.)  
S05E, 55.52', P. Pole (fd nail w/tag W. fc.)  
N34W, 59.25', Fnc. Post (fd nail w/tag E. side)

Signed by *Eugene Farrier*  
Surveyor's Michigan License No. 24594

Date 12-22-93



FORM 20

MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197  
REVISED MAY 14, 197  
REVISED JAN., 198