

FEB 18 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 KALKASKA COUNTY, MICHIGAN

For corners in

KALKASKA

(County)

1993 REMONUMENTATION

Located In:

Corner Code F-11

1993 DEC 22 PM 1:31

Joan Hase
REG. OF DEEDS

1. Public Land Survey T 27N R 7W F-11
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, EUGENE FARRIER, in a field survey on DEC. 1, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

F-11 cor. common to Sec. 28 & 33, T27N-R7W
1850 GLO re-survey: set post, Beech 14", N20E, 13; Beech 6", S21W 18.
9-25-1882, E. Mosher, Co. Surv., visited cor. no accessories.
5-23-01, W.S. Merrill, Co. Surv., visited cor. no accessories.
7-31-07, W.S. Merrill, Co. Surv., visited cor. no accessories.
MSHD, found 1 1/4" pipe, witnesses, Pg 58 of Survey Book (enter 1982).
1972, Gourdie Fraser & Assoc. set PK nail midway and on line.
6-19-72, D.R. Verba, fd nail, replaced with 5/8"x18" re-bar, Liber 1 Pg 106 of Surv.
10-18-72, LCRC Liber 1 Pg 113.
1-5-73, LCRC Liber 1 Pg 162.
8-26-76, J.L. Fletcher, fd 3/4" rod, Liber 1 Pg 177 of Surv.
8-18-78, LCRC fd 1 1/4" well point bent and broken. Replaced and raised with 5/8"x24" re-bar and RLS cap. Referred to witnesses of previous LCRC. Witness did not fit this corner but were for corner MOL. 1 1/4" well point was located 4.8' West and 1.5' South of point MOL.
7-12-79, J.L. Fletcher, fd 3/4" rod MOL, Liber 2 Pg 365 of Surv.
3-9-87, E. Farrier, fd 5/8" rod, Liber 3 Pg 101 of Surv.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-11 cor. common to Sec. 28 & 33, T27N-R7W
Found 5/8" re-bar 1' South of C/L Tyler road & in line w/ fnc to South and 1.5' South and 4.8' West of 5/8" re-bar set MOL by D.R. Verba in 1972.
Old MSHD witnesses and GLO witnesses were not recoverable.
On 12-16-93 the Kalkaska Co. peer group approved the above monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11 cor. common to Sec. 28 & 33, T27N-R7W
Fd. 5/8" re-bar, set brass cap on same, 0.6' below surface.
N76E, 4.98', 1/2 re-rod, fd.
N74W, 118.87', Con. Power Co. Pipeline marker (set "X").
N57W, 210.06', P. Pole, fd.
S06W, 36.81', Nail in cor. fnc. post, set.
N33E, 71.15', 4" R. Pine, set.

Signed by

Eugene Farrier

Date 12-22-93

Surveyor's Michigan License No.

24594

