LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		
Kalkaska Located In:	Corner Code #	
1. Public Land Survey	27N_R_8WA-7 R	
2. Property Controlling S T		
in Section ST_	R	
3. Miscellaneous S T_ Property in Sec. S T_	R R	
rioperty in Sec.		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		ABCDEFGHÍJKĽM
5. Private Claims		1 2 6 5 4 3 2 1
I, <u>Craig W. McVean</u> , in a field survey on	May 26, 1999 do hereby state	3
that under requirements of P.A. 74, Michigan P.A.	of 1970, the corner points	4 7 8 9 10 12
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States		S
Department of the Interior, Bureau of Land Manage Law and /or that the comer points mentioned in line	ement or by a decree of a Court of	6 18 17 16 15 14 13
conformance with the rules of the Michigan Board	of Land Surveyors or by a Decree	8 19 20 21 22 23 24
of a Court of Law; established, re-established, more expressed below:	numented, recovered, found as	9
		10 30 29 28 27 25
NOTE: Not more than 2 corners, all in t	he same town and range, may be recorded on	11
this certificate.	,,,,,	12 31 32 33 34 35 36
•		13
A. Description of original monument and accessories and/or subsequent restoration:		
White Pine 20" N50°W 09 links, Yellow Pine 18" S35°W 77 links GLO, T27N, R8W – L. Lyon - 1850 White Pine 28" N89°E 20 links, Yellow Pine 16" S21°E 42 links - 1934, M. Schaaf +/- index fnd 1967, K.J.Ostling - MDNR Cor. Rec. – Fnd. pipe in concrete mon. per M.Schaaf 1934. SW USBT stp. in place with axe marks falls in line with fire lanes all directions. Good original corner. Set 1" pipe with 4" alum cap. 6" Red Pine S41°W 60.6', 18" Red Pine S52°E 30.3', 9" Jack Pine N45°E 26.9', - 1967, Consumers Power Co. P. Perla – Fnd concrete mon. 10" Pine N46.5°E 27.0', 18" Pine S52.5°E 30.5', 6" Pine S41°W 60.6' - 1973, LCRC L.1, pg.166 - Kal. Co. Rec J. Wilcox – Fnd. DNR Mon. 8" below ground N45°E 27.32' 10" Jack Pine, S52°E 30.64' 18" Red Pine, S41°W 60.86' 7"Red Pine		
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:		
A-7 - Standard corner common to sec. 13 & 24, T27N,R9W and Sec. 1& 19 T27N, R8W-Found 4" DNR Aluminum cap in intersection of firelanes, down 1'. Also found SW Yellow Pine GLO BT stump, well preserved with hack marks. Schaaf recovered this corner position in the 30's. Position does not fit GLO SW BT stump exactly so Schaaf probably had found evidence of the corner monument. DNR monument accepted as a careful and faithful perpetuation of the position of the original corner.		
C. Description of monument for corner and	accessories established to perpetuate locating the	e position of the corner:
alongside. Reset Schaaf mon. – dovbrass cap on 2 ½" X 30" galvanized S52°E 30.87' to set nail and tag S42°W 60.89' to set nail and tag N36°E 29.87' to set nail and tag N52°W 30.38' to set nail and tag East 33' to set Blue Carsonite Pos S32°W 52.2' to face of hack marks of	g in NW side 10" Red Pine (KJO, CPC, JW g in NW side 8" White Pine scribed "XBT' g in SW side 3" Red Pine t w/location tag on 18" +/- Y. Pine stp. (GLO)	Grand Traverse Co. Remon.' OF MICHIGATOR CRAIG W. McVEAN
Signed by Cruic, M. M.	Wen Date_	1/3/2000 P. No.
Surveyor's Michigan Lacense No. 39088		39088
	FORM APPROVED BY MICHIGAN ST	TA TA. (N Y AP
		REVISED JAN., 1983
		REVISED OCT., 1995