

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27 N.R. 8 W


Kalkaska COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 20-29

CORNER MONUMENT Set Cons. Dept. Mon.

DATE MONUMENT PLACED AND WITNESSED 9/19/67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

10" R. Pine S 71 E 49.5'

12" Elm S 50 W 22.5'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey of Section 20. Found 1" pipe with concrete base in center of E-W fireline, as established in previous survey by Marcus Schaaf. Remains of probable SE USBT Hemlock stump in place. Falls in line with fireline south.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE 9/20/67
REGISTERED LAND SURVEYOR #10068