



8 0 2 7 6 4 4

Tx:4019195

5/23/2013 2:19:00 PM

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska

(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S 2	T 28N	R 5W	8, 15
	S	T	R	
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on May 14, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8 – CW 1/16 corner section 2

None

15 – W 1/16 corner common to sections 2 & 11

1978 – LCRC Liber 2, Page 51, – C.F. Roser, PS #12028 – Established 1/8 cor. equidistant & on line between Sec. cor. West & 1/4 Cor. East. – Set 5/8" X 36" re-rod W/ plastic cap & cedar post W/ Loc. Tag. –

- 1) 9" Maple N53°E 24.2'
- 2) 4" Maple in clump S24°E 6.8'
- 3) 11" Maple N30°W 43.9'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8 – CW 1/16 corner section 2

Set a stamped 2" aluminum cap on 5/8" x 34" rebar per standard BLM procedure. Accepted set 2" aluminum cap on 5/8" x 34" rebar as the best available evidence of the position of the corner.

15 – W 1/16 corner common to sections 2 & 11

Found 5/8" rebar and cedar post (poor condition) with location tag. Position of 5/8" rebar fits Roser accessories. Added a stamped 2" aluminum cap to 5/8" rebar and is accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 – a stamped 2" Aluminum Cap on 5/8" x 34" rebar.

S72°E 22.53' to set nail & tag in N. side 12" twin S. Maple  
S05°E 10.25' to set nail & tag in E. side 7" S. Maple  
S88°W 25.99' to set nail & tag in N. side 21" W. Pine  
N04°W 20.05' to set nail & tag in E. side 3" Beech  
Set blue post with location tag 1' Northeast

15 – a stamped 2" Aluminum Cap on 5/8" rebar.

N54°E 24.41' to set nail & tag in NW. side 13" S. Maple (#1)  
S22°E 7.43' to set nail & tag in W. side 14" S. Maple in clump (#2)  
S55°W 69.14' to set nail & tag in SE. side 8" & 10" twin S. Maple  
N28°W 44.25' to set nail & tag in SW. side 16" S. Maple (#3)  
Set blue post with location tag 1' Southeast

Signed by:

Surveyor's Michigan License No.: 46659



Date:

5-23-2013