

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>28</u> N. <u>5</u> <u>W.</u> R. <u>5</u> <u>W.</u>	K-12; K-13; M-13
2. PROPERTY CONTROLL- ING IN SECTION <u>35</u>	T. <u>28</u> N. <u>5</u> <u>W.</u> R. <u>5</u> <u>W.</u>	I
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. S. _____ W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Nov. 4, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:-

C. (continued)

I
Drove 5/8" X 36" R.Rod
Ced.post w/Loc. Tag.
9" Tw.R.Pine N86°W 21.2
12" R.Pine S48°W 46.0
10" R. Pine S38°E 15.7
14" R.Pine N57°E 49.2
Ctr.Power Line (NW-SE)
Due S. 330'+5'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- K-12 Fd. 1 1/4" by M. Schaaf (1946), which fits his wits. Schaaf had U.S.B.T. stump with partial lower face.
- K-13 Recovered 1" pipe from previous Dept. Survey (1951) which perpetuated M. Schaaf Cor. (1943). Set from original B.T. sites. E-W Co. Rd. #612 is N. 29'+.
- M-13 Recovered D.N.R. Mon. from previous Dept. Survey (of 1951) which perpetuated M. Schaaf Cor. set from original U.S.B.T.'s.
- I Estab. 1/8 Cor. per Standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-12	K-13	M-13
Fd. 1 1/4 pipe & set	Fd. 1" pipe & replaced it with	Fd. DNR Mon. & Ced. post
DNR Mon. & ced. post	DNR Mon. ced.post	P.Pole N15°W 18.15
7" W.Pine N45°E 53.4	14" R.Pine S64°E 55.43	8" R.Pine N41°E 109.35
8" W.Pine N38°W 70.2	18" R.Pine S16°W 72.00	12" R.Pine S40°E 97.89
14" R.Pine S04°E 93.8	10" R.Pine S46°W 68.03	10" R.Pine S23°W 127.79
14" R.Pine S48°E 79.5	P. Pole N39°W 86.13	Ctr. Co. Rd. #612
Trail rd. (NW-SE)		Due S 30'+
N52°E 75'+		

SIGNED BY

Carl F. Roser

DATE

3-31-78

SURVEYOR'S MICHIGAN REGISTRATION NO.

12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY

DATE

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

BLUE LAKE TOWNSHIP
KALKASKA COUNTY