

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF-- | LOCATED IN-- | CORNER CODE NUMBER |
|---|------------------|---|
| 1. PUBLIC LAND SURVEY | T. 28 N. R. 5 W. | K-5; K-7 |
| 2. PROPERTY CONTROLLING IN SECTION 14 | T. 28 N. R. 5 W. | 14 |
| 3. MISCELLANEOUS PROPERTY IN SECTION 14 | T. 28 N. R. 5 W. | *on E. line S-14, 662.98-S, of K-5 ¢ 1988,92-N of K-6. |
| 4. LOT NO. _____, RECORDED PLAT _____ | | |
| 5. PRIVATE CLAIMS _____ | | |

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Corey J. Hughes, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 30, 19 76, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on August 3, 1976, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent restoration.~~

C. (continued)

*

| | |
|--|------------|
| Set 3/8"x1/2"x30" iron & Ced, Post w/Loc Tag | |
| 4" Maple Clmp. | N38°E 9.0 |
| 10" Maple | S49°E 20.2 |
| 10" Maple | S44°W 12.3 |
| N-S R/L | 1.6' East |
| Trail Road | 150'± East |

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-5 Set DNR mon. by witnesses of Marcus Schaaf, as set in 1946 from original B. T. sites.

K-7 Fd. pipe in concrete set by Marcus Schaaf, RLS, replaced with DNR monument. Schaaf notes indicate U.S.B.T. sites.

14 Established 1/16 cor. equidistant & on line between 1/4 Cor. N. & Sec. Cor. S.

* Established the SE corner of N1/2 of NE1/4 of NE1/4, Section 14; per Std. B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| K-5 | K-7 | 14 |
|----------------------------------|-----------------------------|--|
| Set DNR mon. & ced.post & stones | Set DNR mon. & cedar post | Set 3/8"x1/2"x60" iron pipe & ced.post w/Loc Tag |
| New Witnesses | 6" Triple Maple S35°E 38.8 | 10" Beech N20°E 25.7 |
| 12" Twn.Basswood N04°E 23.4 | 10" Triple Maple S36°W 40.8 | 6" Maple S35°E 14.1 |
| Clmp (6) Basswood S06°W 13.5 | 12" Twn.Beech N72°W 30.7 | 5" Maple S05°W 29.0 |
| Clmp (6) Basswood S47°W 22.0 | R/L West from Corner | N-S R/L 0.45' East |
| R/L East 1.5' South | | |
| R/L South 1.8' East | | |
| 8" Maple in Clump S50°E 86.5 | | |

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FOR STATE AND UNITED STATES AGENCIES:

Above corners by Corey J. Hughes, R.L.S. #20706; Title X Survey for Michigan, Summer, 1976

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Carl F. Roser 1-16-78
MICHIGAN REGISTERED LAND SURVEYOR

Carl F. Roser

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

BLUE LAKE TOWNSHIP
KALKASKA COUNTY