

\$7.00  
\$2.00 COMMISSION

SEP 17 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
KENT COUNTY REMONUMENTATION

For corners in

Kent  
(County)

Located in:

Corner Code #

1. Public Land Survey

T 5N R 12W

G-9

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

REC. OF DEEDS

95 AUG 28 AM 10:51

STATE OF MICHIGAN  
COUNTY OF KENT  
RECEIVED FOR RECORD

8612

Register of Deeds Stamp & File Number

I, Randy Kolehhouse, in a field survey on April 11 19 95,  
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points  
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required  
in the current manual of survey instructions of the United States Department of the Interior, Bureau of  
Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,  
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,  
found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-9	1831	G.L.O. Notes	Mullett	Set Post
	1963	Wit. Map	K.C. Surveyor	Iron Center Line Conc.
	1971	Wit. Map	K.C. Surveyor	Iron Center Line Conc.
	1974	L.C.R.C. #703	Exxel Engineering	Found 3/4" Iron in Mon. Box.
	1981	L.C.R.C. #1646	Nederveld & Jonker	Found 3/4" Iron in Mon Box/Set K.C. Monument
	1988	L.C.R.C. #4612	Olson, Meyers & May	K.C. Monument

P.A. 345 1990 KENT COUNTY

PEER APPROVED 5/25/95

CHAIRMAN Harry Huber

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Nederveld & Jonker on 2/21/81 and was recorded per L.C.R.C. #1646.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-9 Found standard Kent County Monument in monument box at C/L intersection of Byron Center Avenue running N-S and 92nd Street running E-W per L.C.R.C.'s #1646 and #4612 as set by Nederveld & Jonker in place of a 3/4" iron in monument box they found which checks L.C.R.C. #703 and K.C. Surveyor's Wit. Map (1971).

L.C.R.C. #1646

Nail & Remon. tag on W side P. pole WSW 127.30'  
Nail & Remon. tag on NE side guy pole NW 47.11'  
Nail & Remon. tag on NE side P. pole SE 41.33'

L.C.R.C. #4612

Nail & Remon. tag on N side P pole S 80 W 127.30'  
Nail & Remon. tag on NE side guy pole N 45 W 47.11'  
Nail & Remon. tag on NE side P pole S 40 E 41.33'  
Nail & Remon. tag on E side T pole N 20 E 97.11'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9 Standard Kent County Monument

Nail & K.C. remon. tag on NE side P. pole S 40° E 41.52'  
Nail & K.C. remon. tag on NE side guy pole N 45° W 47.11'  
Nail & K.C. remon. tag on W side P. pole S 80° W 127.30'  
Nail & K.C. remon. tag on E side T. pole N 20° E 97.19'

Signed by

Randy J. Kolehhouse  
EARTH TECH

Date

8/21/95

Surveyor's Michigan License No.

25854

