

SEP 16 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

- | | | | |
|---------------------------------------|-------------|--------------|------------|
| 1. Public Land Survey | T <u>5N</u> | R <u>12W</u> | <u>I-8</u> |
| | T _____ | R _____ | _____ |
| | T _____ | R _____ | _____ |
| | T _____ | R _____ | _____ |
| 2. Property Controlling
in Section | S _____ | T _____ | R _____ |
| | S _____ | T _____ | R _____ |
| 3. Miscellaneous
Property in Sec. | S _____ | T _____ | R _____ |
| | S _____ | T _____ | R _____ |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Randy Kolehouse, in a field survey on April 6 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners; all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-8	1831	G.L.O. Notes	Mullett	Set Post	P.A. 345 1990 KENT COUNTY
	1941	Wit. Map	K.C. Surveyor	Iron	PEER APPROVED <u>5/29/95</u>
	1972	L.C.R.C. #257	Exxel Engineering	Found 1/2" Iron	CHAIRMAN <u>Randy Kolehouse</u>
	1972	L.C.R.C. #333	Williams & Works	Found 1/2" Iron	
	1981	L.C.R.C. #2306	Nederveld & Jonker	Found 1/2" Iron/Set K.C. Monument	
	1991	L.C.R.C. #6332	Chris Marshall	K.C. Monument	

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Nederveld & Jonker on 9/1/81 and was recorded per L.C.R.C. #2306.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- I-8 Found standard Kent County Monument 8.0' East of C/L of Burlingame Avenue running N-S per L.C.R.C.'s #2306 and #6332 as set by Exxel Engineering in place of a 1/2" iron they found which checks L.C.R.C.'s #257 and #333 and K.C. Surveyor's Wit. Map.

L.C.R.C. #2306

NW cor. hse #8794 N48°E 64.67'
Nail & K.C. Remon. tag S side T. pole S70°E 23.02'

L.C.R.C. #6332

Nail & Tag NE sd. 36" Maple S 30° E 31.64'
Nail & Tag W sd. 20" Elm N 7° E 81.46'
Nail & Tag S sd. U.P. S 67° E 23.10'
Nail & Tag S sd. U.P. N 82° W 115.50'
NW cor. Hse #8794 N 48° E 64.66'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- I-8 Standard Kent County Monument

Nail & K.C. remon. tag on NE side 36" Maple S 30° E 31.64'
Nail & K.C. remon. tag on W side 20" Elm N 07° E 81.46'
Nail & K.C. remon. tag on S side Utl. pole S 67° E 23.10'
Nail & K.C. remon. tag on S side Utl. pole N 82° W 115.50'
NW cor. hse #8794 N 48° E 64.66'

Signed by Randy J. Kolehouse Date 8/21/95

EARTH TECH

Surveyor's Michigan License No. 25854

STATE OF MICHIGAN
REGISTERED LAND SURVEYOR
RECEIVED FOR RECORD
5/29/95 AM 10:53
8631

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

