

COMMISSION

SEP 13 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

1. Public Land Survey

T 5N R 12W

M-5

2. Property Controlling
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

REG. OF DEEDS

8668

95 AUG 28 AM 10:55

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

Register of Deeds Stamp & File Number

I, Randy Kolehhouse, in a field survey on April 15 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-5	1817	G.L.O. Notes	L. Lyon	Set Post
	1962	Wit. Map	K.C. Surveyor	Boat Spike
	1973	L.C.R.C. #477	Williams & Works	Found 1" Iron in Mon. Box
	1980	L.C.R.C. #1528	Exxel Engineering	Found 1" Iron in Mon. Box/Set K.C. Monument
	1991	L.C.R.C. #6365	Chris Marschall	K.C. Monument

P.A. 345 1990 KENT COUNTY

PEER APPROVED 6/27/95

CHAIRMAN Randy Kolehhouse

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering on 12/4/80 and was recorded per L.C.R.C. #1528.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-5 Found standard Kent County Monument at the C/L intersection of Diviison Avenue running N-S and 76th Street running E-W per L.C.R.C.'s #1528 and #6365 as set by Exxel Engineering in place of 1" iron in monument box they found when checked L.C.R.C. #477 and K.C. Surveyor's Wit Map.

L.C.R.C. #1528

L.C.R.C. #6365

SE corner brick gas station N50°W 82.22'
Most N'ly corner of 1' x 1' brick pillar of gas station
S 45°W 124.11'

SE Cor brick gas station N 50 W 82.16'
Nail & Tag U.P. NW side S 40 W 58.61'
Nail & Tag U.P. N side N 50 E 64.15'
N. Cor 1' x 1' Brick Pillar of gas station S 45 W 124.05'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5 Standard Kent County Monument

North cor. of 1' x 1' brick pillar at N cor. bldg. #7609 S 45° W 124.05'
SE cor. brick bldg. #7585 N 50° W 82.20'
Nail & K.C. remon. tag on SW side Guy pole N 20° W 60.16'
Nail & K.C. remon. tag on NW side P. pole N 50° E 64.13'
Nail & K.C. remon. tag on NW side P. pole S 40° W 58.59'
Nail & K.C. remon. tag on SW side P. pole S 40° E 67.39'

Signed by Randy J. Kolehhouse
EARTH TECH

Date 8/21/95

Surveyor's Michigan License No. 25854

