For corners in

MAR 08 1999

KENT	COUNTY	REMONUM	MENTA	TION
	~ ~ ~ ~ ~ ~	TOTALOTACIA	11 /1 1 1 / 1	TIOI.

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ATE 970	REG. OF DEEDS	twis Dand	8 OCT -7 AN IO: 15	ECEIVED FOR RECORD	· []	
0+1	1-4	^	co	le	4	1

ω


KENT COUNTY Located In: Corner Code # (County) 1. Public Land Survey 2. Property Controlling T 9N R 12W Wit. Mon. on in Section 3. Miscellaneous Property in Sec.

10705 Register of Deeds Stamp & File Number

, Recorded Plat 5. Private Claims

Kirk Breitels , 19⁹⁸ Sept. 11 in a field survey on . do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

No Information - Not Set

See LCRC # 10704 for N 1/4 corner (D-1) of Section 5 - falls in soybean field.

P.A. 345 1990 KENT COUNT P.A. 345 1990 NEW 9/24/98.
PEER APPROVED 9/24/98.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established a point on the N-S 1/4 line for placement of witness monument for D-1 (N-S 1/4 line per LCRC #6885)

Computed N 1/4 corner is North 593.45' Central 1/4 corner is South 1974.60'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Harrison Monument with witness cap at above location SW corner of steel farm building S80°E 73.87 SW corner concrete block farm building N55°E 98.04 NW corner barn foundation N40°E 160.00' Nail & KC Remon. tag W. side P. Pole N25°E 65.96 Capped Rerod (Bueche) - 0.07' West of line North 88.77 SE corner house siding N60°W 97.83' Nail & KC Remon. tag W. side P. Pole S15°E 161.38' In C/L N-S asphalt road

OF MICHIGA KIRK BREITELS LAND SURVEYOR 3007 SFOLAND

Signed by 30077

Surveyor's Michigan License No.

9/24/98