

\$7.00  
\$2.00

MAY 22 2000

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KENT COUNTY  
(County)

Located In:

Corner Code #

1. Public Land Survey

T10N R12W

Tyrone Twp.  
B-9

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat  
5. Private Claims

Kirk Breitals, in a field survey on Jan. 19, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

|          |               |           |                                      |
|----------|---------------|-----------|--------------------------------------|
| B-9 1837 | GLO           | Whitcomb  | Set Post                             |
| 1962     | Kent Co. Wits |           | "T" Iron                             |
| 1981     | LCRC #2079    | Nederveld | 3/4" Iron in Mon. Box                |
| 1983     | LCRC #3429    | Bueche    | Set Kent County Monument in Mon. Box |
| 1994     | LCRC #7578    | J. Glaza  | Kent County Monument                 |

P.A. 345 1990 KENT COUNTY  
PEER APPROVED 2/25/99  
CHAIRMAN *[Signature]*

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John C. Bueche on 5-17-83 and was recorded per LCRC #3429.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-9 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by John C. Bueche in place of the Iron he found inside a Mon. Box. Said Iron checks with Kent Co. Wits. and LCRC #2079.

LCRC #3429

LCRC #7578

|                                |               |                                |               |
|--------------------------------|---------------|--------------------------------|---------------|
| "X" cut on S. end conc. culv.  | S75°E 144.08' | "X" cut on S. end conc. culv.  | S75°E 144.08' |
| "X" cut on N. end conc. culv.  | N80°E 144.47' | "X" cut on N. end conc. culv.  | N80°E 144.47' |
| Nail & Remon. tag Tri. 10" Ash | S10°W 36.47'  | Nail & Remon. tag 12" Tri. Ash | S10°W 36.47'  |
| Nail & Remon. tag fence post   | N30°W 58.23'  | NE corner brick porch pillar   | S25°E 128.66' |
| NE cor. brick porch pillar     | S25°E 128.66' |                                |               |

C/L blacktop road E-W is N. 1.2' ±

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-9 Standard Kent County Monument in Mon. Box

|   |               |
|---|---------------|
| "X" cut on S. end concrete culvert        | S75°E 144.08' |
| "X" cut on N. end concrete culvert        | N80°E 144.47' |
| Nail & KC Remon. tag W. side Tri. 12" Ash | S10°W 36.47'  |
| NE corner brick porch pillar              | S25°E 128.66' |
| C/L blacktop road E-W is North 1.2' ±     |               |
| C/L gravel drive North is West 18' ±      |               |



Signed by *[Signature]*  
Surveyor's Michigan License No. 30077

Date 2/25/99