

\$7.00
\$2.00

MAY 22 2000

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KENT COUNTY
(County)

Located in:

Corner Code #

1. Public Land Survey

T_{10N} R_{12W}

Tyrone Twp.

G-6

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Kirk Breitels, in a field survey on Sept. 22, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-6 1837	GLO	Whitcomb	Set Post
1940	Kent Co. Wits		Concrete Monument
1976	LCRC #902	McCloskey	3/4" Iron
1983	LCRC #3434	Bueche	Set Kent County Monument
1994	LCRC #7568	J. Glaza	Kent County Monument

P.A. 345 1990 KENT COUNTY

PEER APPROVED 9/23/99

CHAIRMAN [Signature]

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John C. Bueche on 5-18-83 and was recorded per LCRC #3434.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-6 Found BROKEN Kent County Monument (Harrison) per witnesses from above LCRC as set by John C. Bueche in place of the RR Spike & Conc. Mon. he found. Both RR Spike & Conc. Mon. check with Kent Co. Wits. and LCRC #902. Removed and Reset Kent County Monument in Mon. Box.

LCRC #3434		LCRC #7568
"V" cut NW leg of tower	S15°E 130.03'	"V" cut NW leg of tower S13°E 130.00'
PK Nail P. Pole	N55°E 184.72'	Nail & Remon. tag P. Pole N65°E 184.66'
Nail & Remon. tag 8" Elm	S85°W 57.59'	Nail & Remon. tag P. Pole S70°E 179.04'
Nail & Remon. tag 3" Poplar	S35°W 116.95'	Nail & Remon. tag 6" Tree S87°W 37.39'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-6 Standard Kent County Monument in Mon. Box

"V" cut on tower leg (3' high)	S13°E 129.95'
Nail & KC Remon. tag S. side P. Pole	N65°E 184.66'
Nail & KC Remon. tag N. side P. Pole	S70°E 179.04'
Nail & KC Remon. tag N. side 10" Tree	S87°W 37.30'

C/L N-S asphalt road is 2' West ±



Signed by [Signature]

Date 10/28/99

Surveyor's Michigan License No. 30077