SURVEY & REMONUMENTATION

MAR 1 9 1997

___ , Recorded Plat _

5. Private Claims ____

expressed below:

LAND CORNER RECORDATION CERTIFICATE

Filing Requi	rement of	Act 74.	Mich.	P.A.	1970


,	. 1.	Filing Requirement of Act 74, Mich. P.A. 1			
	r corners in Keweenaw	COMMISSION Located In:	Corner Code ≠≠		
1.	Public Land Su	T 57N R 30W T 57N R 30W	D3 MC D3-E3(3)		

REGISTER'S OFFICE
County of Keweenaw SS 1
Received for Record, the 12
day of Mayon hon Ary 10 11
at 9:00 o'clock A.M., and Recorded
in Liber / of LCR
on page 148
- marily lymount
() Register of Deeds

R 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

Steven C. Hein	in a field survey on	June 28, 1996	, 19 ,
	r requirements of P.A. 74, Michig		
in lines 1 and 2 above we	re in conformance with regulat	ions and rules there	fore as required in the
current manual of survey i	nstructions of the United States	S Department of the li	nterior, Bureau of Land
Management or by a decre	e of a Court of Law and/or that th	e comer points menti	ioned in lines 3, 4 and 5
above were in conformand	e with the rules of the Michigan	Board of Land Survey	yors or by a Decree of a
Court of Law; established	d, re-established, monumente	ed, re-monumented,	recovered, found as



NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: (D-3) From Original Notes: 40.00 Set qr. Section post; Sugar 12 S82W 32; do 12 N41E 28: No evidence of original corner or accessories. (D-3/E-3)H.C. From Original Notes: 53.15 Intersected Lake Set Meander post; Yellow Birch 10 N81W 14; Fir 6 S82W 26: No evidence of original corner or accessories.

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (D-3) Found Bit end of 1" hex drill rod. Witnesses of record: 8" Pine NBOE 8.44"; 14" Maple S50W 11.58"; 4" Pine 545E 6.33" (D-3/E-3)M.C. Found 1 1/4" pipe over 1" pin, 25' West of Gratiot Lake. No apparent witnesses.

> Ratified by Peer Group In accordance with P.A. 345

	Description of monument for	corner and	d accessories established to perpetuate locating the position of the corr	ner:
7 -				

(D-3) Accepted location of drill rod Replaced with 4° Remon. Brass Cap

stamped for corner

Witnesses (New): 10° H. Maple N25E 16.80°

3' H. Maple S40E 16.52' 14" H. Naple S48W 11.61'

16" H. Naple N49W 33.66" Note: Wit. have tag #32336 (D-3/E-3)M.C. Accepted location of 1°

pin, Replaced with 4° Remon. Brass

Cap stamped for corner

Witnesses:

16' Elm N17E 32.24'

14" Ash \$35W 60.23"

4" Oak S73W 36.69'

9" Balsam N30W 37.08'

Note: Wit. have tag #32336

C. HEIN SURVEYOR No. 32336

igned by Stewn C. Stein	Date	<u>5</u> ,
urveyor's Michigan License No		

18ER 13, 1996