DEC 1 6 1998

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 SECTION OFFICE County of Keweenaw SS For corners in Keweenaw (County) Located In: Corner Code ## Received for Record, the day of December A. D. 1998 57 R _ 57 R _ 1. Public Land Survey at //:000'clock A. M., and Recorder in Liber. 2. Property Controlling on page. Waila in Section Miscellaneous Register of Deeds Staggister of Normal Property in Sec. ___ , Recorded Plat _ 5. Private Claims _ i, John I. Haataja , in a field survey on 11/30 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: MC10 Meander corner between Section 32&33 MC11 Meander corner between Section 32,T57N-R33W and Section 5, T56N-R33W. 10" Spruce used for meander corner in 1846 by Samuel Hill. T57N-R33W. Wood post set for meander corner in 1846 by Samuel Hill. 9" Spruce SO7°W 18 lks 18 1ks 8" Cedar N80°E 26 1ks. 12" Spruce 15 1ks. S27°E B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: MC11 No evidence of original or other corner MC10 found 14' iron pin in concrete set by Holland in 1917. found. Set meander corner S89°-53'-54"W of section corner 32/33, and on intermediate traverse line of Calumet Lakeshore Plat of Survey. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
MC10 Established a witness corner
MC11 Established meander corner by placing a
24.67 feet South of meander corner

1" iron pipe with a 4" brass cap stamped by placing a 1" iron pipe with a 4" Keweenaw County Remonumentation Point. brass cap stamped Keweenaw County 4" Cedar S39°E 8.65' Remonumentation Point. 16" W. Birch N39°E 5.82' 5" Cedar N82°W 9.99' 11 " iron pin in concrete North 24.67' 4" Maple N52°E 6.55' 5 ^H S33°E 5.30 14" W. Birch S37°W 27.81' Cedar 8" S48°W 31.35' Cedar JOHN I. ALATAAH 12/2/98 Signed by Date LAND SURVEYOR Surveyor's Michigan License No.

NO.

19833