## SURVEY & REMONUMENTATION

APR 2 8 1995

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requirer	ment of Act 74, Mich.	P.A. 1970IS	STER'S OFFICE )	
			County	y of Keweenaw SS +	
Keweenaw	Located In:	Corner Code =++	Receiv	ved for Record, the 20	
·			day of_	January A.D. 1995	
1. Public Land Survey	T_58N_R_32W	C 12/13	at <u>/0</u> -	30 o'clock 1 M., and Recorded	
1. Tubilo Edila Galvey	TR	<u> </u>	in Libe	erl_of_LCK	
	TR	Other #8 V	on page	e 128 · ·	
·	T R	<u> </u>		Janly Vengues	-
2. Property Controlling	S T R			Register of Deeds	
in Section	S T R		10		
3. Miscellaneous	S T R				
	5 I R		Regis	ster of Deeds Stamp & File Numbe	r
Property in Sec.	S T R		<u> </u>		
A Labbia	5 1.15	· · · · · · · · · · · · · · · · · · ·			
5. Private Claims	Recorded Plat			ABCDEFGHIJK	L
5. Private Claims				2	
			- 1		-[
		j*:		3	+
. John I Haataja	Dece	umbar 1 OA		4 7 7 8 9 10 10 1 1	<b>—</b>  2
do boroby cortify that yadar -	in a field survey on Dece	ember 1, 19 94		5	_
in lines 1 and 2 above were	equirements of P.A. 74, Michigan P.A. of in conformance with regulations and	1970, the corner points men	tioned	6 18 17 16 15 14	— is-
current manual of survey inst	tructions of the United States Department	ent of the Interior. Bureau o	fland	7	
Management or by a decree o	f a Court of Law and/or that the corner p	points mentioned in lines 3, 4	and 5	8 3 30 31 33 33	
above were in conformance w	rith the rules of the Michigan Board of L	and Surveyors or by a Decre	ee of a	9   19   20   21   22   23	24-
court of Law; established, expressed below:	re-established, monumented, re-mo	numented, recovered, four	nd as		$\neg$
			i : :1	0 30 29 28 27 26	-25-
	corners, all in the same town and	range, may be recorded	11	11	+-
on this certificate	<b>'</b> •		12	2 31 32 33 34 35	—36-
			13	3 9 1 1 1 1 1	
<ol> <li>Description of original</li> </ol>	monument and accessories and/o	or subsequent restoration	ווו		
C 12/13 Meander	Corner between Sec. 31	& 32 <sub>-</sub>			
	otes: Set M.C. at 5" Mo				
5g	Y. Pine 20" S 50°	W 1/1 1kg			
	Fir 11" \$ 70°	F 28 1kc			
	111 11 3 70	L 20 1KS.			
		: !			
	•	:			
<ol><li>Description of corner e</li></ol>	evidence found and/or method app	olied in restoring or reest	ablishing cor	rner;	
C 12/13 Meander	Connon bottoon Con 21 (	20			
No trace	Corner between Sec. 31 8	X 32.			
NO trace	of original corner four	nd.			
ke-estab	lished Section line from	n natural feature			
cairs,	as noted in original no	otes.	-		
		•			
				Ratified by Peer Group	
			·	In accordance with P.A. 345	
			•	Co. Rep. Ames M Double	
				W. Rep. Frag.	_
			D	Date	
		•			
			·		
<ul> <li>Description of monume</li> </ul>	nt for corner and accessories esta	blished to perpetuate loc	ating the no.	sition of the corner:	
C 12/13 Witness (	Cornen Meander Corner be	tween Sec. 31 & 3	2.	or the comer.	
Set 1" p <sup>.</sup>	ipe with brass cap as a	careful and faith	ful	400 50 50 10 10 10 10 10 10 10 10 10 10 10 10 10	
re-estab	lishment of the position	of the original	Section	E 0 1/01	
line.	p =	or one or iginar	30001011		
18" W.	Pine S 63° E 48.85'	:		JOHN!	P
	Spruce N 88° W 6.83'	•	: 1	HAATAJA V	923
8" W.	Spruce N 42° E 32.45'	•		LAND.	
5" Ced	dar S 13° W 32.73'			SURVEYOR C	EJ EJ
5 000	J 15 # 52./5			SON NO.	#E
				19833	,
_				PALED TAND SU	
	0 11		:	A PERMANENTAL	
gned by	V. Stonolas	_	D	OI 1004	
	- Hexiex copy	Date	necembe	r 21, 1994	
urveyor's Michigan License	No 19833 <i>U</i>				

PROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983