7.	
2-	

JUL 2 3 1997

COMMISSION	ISSION
------------	--------

		LAND) CORNER REC g Requirement	CORDATION	ICERTIFICAT			
For corners in	n Ross Twp.	PINA	g Keduiteinent	OI ACL 14, W		LIBER	2PAGE	124
Kalama	200	Located In:	Corner Cod	e #		, -		
(0	County)						1 10	→1 C 2
1. Public La	nd Survey	T <u>1S</u> R TR		-08		CL CL	97 APR	STATE O COUNTY OI RECEIVED
		TR			į. I	CLERK		AI P
.	O antrolling	T R		<u></u>			~ J. ~	등 유 이
Property in Section		S TR S TR				REGIS	$\mathcal{J}_{\mathcal{I}} \supset$	K M M
3. Miscellar		S TR				S	E Ukan	& File Mumber
Property	in Se c.	<u> </u>				Register of	Their are find	
4 Lot No.	. Recor	ded Plat				ABCD	E F G H	== =
5. Private C	laims					2 6 5		
						3 3	444	
Robert	E. Snell	, in a field survey on	March 14, 19	94 do hereby :	state that under	4 - 7 - 8) 11 12
requirements	of P.A. 74, Michiga	n P.A. of 1970, the con	ner points mentioned red in the current man	nual of survey ins	structions of the	·5		+ + + + + + + + + + + + + + + + + + + +
United States	Department of the I	nterior, Bureau of Land I	Management of by a c	ce with the rules	of the Michigan	6 -19 -1	16	, 14 13
Board of Lan	d Surveyors or by nd as expressed be	a Decree of a Court	of Law; established,	, re-established	, monumented,	8 19 20	21 2	22324
		ners, all in the same to	un and range may	he recorded		9 /	- - 	
	this certificate.	icis, ai il die sellie se				10 30 -2	28 - 2	7-26-25
						11 12 31 3	2 33 3	4 35 36
						13		
A. Descript	ion of original mo	nument and accesso	ries and/or subsec	quent restoration	on: Section post	t.		
1826:		es Government	Surveyors,	1ks.	ccc (on pos-	•		
	Elm 7" Elm 6"	' N. 02 ⁰	W. 34	lks.				hu ma in
1883:		, County Surve						
	gone. Put	1 ft. of smal	l stones wit	h 2 foot	earthen po	st over fo	r corner	and marked -
	Whitewood :	16" S. 18 ¹ 4 ⁰ E.	148 lks."					
B. Descrip	ation of corner evi	idence found and/or	method applied in I	restoring or re	establishing corn	er:		·
1970:	Wilkins & L Highway M-8	Wheaton Engr. 89. Tile in f	Co.; found tence line Ea	tile in sw ast and 1	wamp 659.74 .2' West of	' South of	South.	the of
1983:	Wilkins & 1	Wheaton Engr.	Co.; found t	tile in su	wamp.	. 7 1	wanned	tile all
1994:	Found 3" re	ound tile with	ı "x" on top	in swamp				_
	rotted off	at surface.			m>2.14	RATIF	IED	NTA 62
					BA KY	ALAMAZC MONIIME	MOITATION	
						PEER G	ROUP ₂₋₂₁	- 10 - 1997
C. Descrip	tion of monumen	t for corner and acce	ssories established	d to perpetuate	e locating the pos	sition of the cor	ner:	• •
C-08:		ost, Section ation Program	DAAM EMAIIN	An Penrua	1'V // . 172/	anu is u	CCCPCCC CC	
		ation rrogram ul perpetuation "x" on top as						
	tile with	"x" on top as laced remonum	entation sle	eve over	LITEL EGG	c eage or	Stamp	East 86' <u>+</u> .
	Nail in Ea	st Side	4" Ma 15" 0	ıple	N. 44 E.	20. 49	00	
	Nail in Ea Exist. Nai	ist Side 11/Tab in East	Side 13" T	amarack	N. 06° W.	27.	88 (Dead)	
	Nail in We	st Side	4" Ma	iple iple	N. 06° W. S. 10° W. S. 50° E.	40. 10.	ეგ [.]	
	Nail in We	est side	4 Ma	ι ρ ι ε		-14-9	7	•
Signed by		c. July	9734		Date			<u></u>
Surveyor's	Michigan Licens	e No	9/34					