

FEB 26 1998

7
2 SECTION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in Richland Twp.
Kalamazoo
(County)

Located In:

Corner Code #

| | | | | | |
|------------------------------------|---|------------|---|-------------|-------------|
| 1. Public Land Survey | T | <u>1S.</u> | R | <u>10W.</u> | <u>A-11</u> |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | R | | |
| | S | | R | | |
| 3. Miscellaneous | S | | R | | |
| Property in Section | S | | R | | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

6. IWM Job No. 26019

I, Allen H. McMachen, in a field survey on June 14, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1827 - John Mullett, D.S., Intersected West boundary 25 lks. North of post. Set post at intersection, corner to Sections 30 & 31, Wh. Oak 18" S. 38° E. 51 lks., Y. Oak 7" N. 46° E. 54 lks..
1887 - F. Hodgman, C.S., "Found stone 3' long set for corner, set post in the East side Y. Oak 6" N. 52° E. 11 lks., Double Hickory S. 58° W. 10" 37 lks..
1905 - Ed Strong, C.S., "Found stone & tile on top."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found bent 1/2" iron at road grade. Dug and found clay tile 2.5' below grade and directly under location of 1/2" iron. Expanded excavation to West and Found very large pointed stone 1.54' West of found tile. Point of stone was about 1' below grade. Uncovered 1.5' of stone and still could not move stone.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found pointed stone on West side of found clay tile is accepted as a careful and faithful perpetuation of the position of the original corner. Placed 0.7' of Harrison Monument over point of stone and set in concrete with monument box over, Accessories:

Iron rod in mon. box (S.E. corner, Sec. 25, Cooper Twp.) South 16.51'
Iron rod S. 85° E. 14.93'
Nail & Tab in Southeasterly side U. Pole S. 55° W. 30.55'
Nail & Tab in Westerly side 10" Hickory N. 25° W. 56.14'
Nail & Tab in Northerly side 10" Hickory S. 70° W. 34.58'

Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 12/10/97

LIBER 2PAGE 263

CLERK - REGISTER

[Signature]

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
97 DEC 22 PM 3 49

Register of Deeds Stamp & File Number

| | | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

**RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
11-20-1997**

[Signature]

