

SURVEY & REMONUMENTATION

JUL 23 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER

2PAGE 131

For corners in Richland Twp.
Kalamazoo
(County)

Located In:

Corner Code #

1. Public Land Survey	T	1S.	R	10W.	E-8
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous	S		T	R	
Property in Section	S		T	R	

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
97 MAY 16 PM 3
CLERK - REGISTER
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
6. IWM Job No. 26689

I, Allen H. McMachen, in a field survey on March 31, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1827 - John Mullett, D.S., "Set 1/4 Section post", Wh. Oak
18" S. 29° E. 71 lks., Wh. Oak 16" N. 04° E. 38 lks.

1871 - F. Hodgman, C.S., "Found stake from roots of one witness, planted post and stone and marked cherry 20"
S. 41 1/2° W. 57 1/2 lks., Hickory 8" S. 13° E. 204 1/2 lks.

1887 - F. Hodgman, C.S., "Found Stone and Brick S.W.
132 lks. from Wh. Ash bearing tree standing, set post.
Hickory 12" N. 54° W., 56 lks.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron rod in monument box. Removed iron and bored inside box to depth of 3' finding clay directly below surface iron.

**RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
4-16-1997**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Clay Tile is accepted as a careful and faithful perpetuation of the position of the original corner. Placed Standard Harrison Monument over found tile, Accessories:

"PK" Nail in N.W. side 30" Hickory N. 25° E. 58.36'
Nail & Tab (existing) in North side 14" Oak S. 70° E. 73.15'
Nail & Tab (existing) in West side 30" Hickory S. 10° W. 96.94'
"PK" Nail in Easterly side 32" Hickory N. 20° W. 90.44'



Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 5/15/97
FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983