

AUG 06 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER

2 PAGE 033

For corners in
Kalamazoo
(County)

Located In:

Corner Code #

Richland Twp.

- | | | |
|--------------------------------------|----------------|------|
| 1. Public Land Survey | T 1 S. R 10 W. | H-07 |
| | T R | |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Section | S T R | |
| | S T R | |

CLERK - REGISTER

James J. Smith

96 JUN 7 PM 2 27

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert E. Snell, in a field survey on February 26, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826: United States Government Surveyors; set 1/4 Section post.

Burr Oak 14" N. 04° E. 10 lks.
Burr Oak 14" S. 70° W. 58 lks.

1887: F. Hodgman, County Surveyor; found stake and stone of former survey. Set post.

Maple 3" S. 42° W. 55½ lks.
Maple 2" S. 49½° E. 69½ lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1936: Wilkins & Wheaton Engineering Co.; found tile brought to surface with iron.

Maple 20" S. 40° W. 35.85'
Maple 16" S. 60° E. 90.22'
Telephone Pole N. 70° E. 72.45'

1976: Douglas W. Hooth, R.L.S. #7966; L.C.R.C. L-1, P-637 found ½" iron over tile in monument box.

31" Maple S. 37° W. 36.88'
Power Pole N. 72° E. 73.19'
Plat Monument S. 01° E. 33.03'

1996: Found ½" x 18" long iron bar in monument box over tile.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-07: South 1/4 post of Section 15, T. 1 S., R. 10 W.; ratified by the Kalamazoo County Remonumentation Program Peer Group on March 21, 1996 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile as set by F. Hodgman, County Survey in 1887 remonumentation survey. Placed 10" or Harrison monument in concrete in monument box over tile.

PK Nail on East Side of 36" Maple S. 44° W. 35.17'
PK Nail on North Side of Light Pole N. 74° E. 74.01'
PK Nail on South Side of 14" Ash N. 60° W. 42.95'
1/2" Iron Bar in Plat Monument S. 04° W. 33.08'

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
3-21-1996

Signed by

Robert E. Snell

Date

6-6-96

Surveyor's Michigan License No.

9734