

SURVEY & REMONUMENTATION

JUL 23 1997

LIBER

2 PAGE 152

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Richland Twp.

Kalamazoo
(County)

Located in:

Corner Code #

1. Public Land Survey

T1S R10W

K-05

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert E. Snell, in a field survey on March 17, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
97 JUN 24 PM 1 17
CLERK - REGISTER

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1826: United States Government Surveyors; set post, corner to Sections 11, 12, 13 & 14.

Wh. Oak 30" N. 45° ? 42 lks.
Wh. Oak 15" S. 10° E. 65 lks.

1887: F. Hodgman, County Surveyor; "Found old stake with stone around in center of road and in line with fence south. Set post".

R. Oak 18" N. 31° W. 40 lks.
Y. Oak 18" N. 75° E. 98½ lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1959: Wilkins & Wheaton Engr. Co.; iron over tile.

Fence Post S. 03° W. 24.0'
Iron Post N. 05° W. 22.1'
14" W. Ash N. 40° E. 22.7'
36" Oak N. 31° W. 25.6'
14" W. Ash N. 60° E. 58.4'

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
4-17-1997

1997: Found ½" x 18" iron over tile. A second iron was found 0.33' East and 0.12' North of iron over tile.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-05: Northwest corner, Section 13, T. 1 S., R. 10 W., ratified by the Kalamazoo County Remonumentation Program Peer Group on April 17, 1997 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found ½" x 18" iron over 3" round tile. Tile was set in 1887 by F. Hodgman, County Surveyor in a Remonumentation Survey. Placed a remonumentation sleeve over tile with a monument box over.

PK Nail in North Face	Fence Corner	South	23.90'
3" Iron	Fence Corner	N. 05° W.	22.10'
PK Nail in East Face	8" Walnut	S. 45° W.	40.25'
PK Nail in West Face	28" Maple	N. 35° E.	21.62'

Signed by

Robert E. Snell

Date

6-18-97

Surveyor's Michigan License No.

9734