

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COOPER TOWNSHIP
KALAMAZOO
(County)

Located In:

Corner Code #

LIBER
2 PAGE 368

CLERK - REGISTER

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
98 OCT 22 PM 1 22

1. Public Land Survey	T	1S.	R	11W.	L-11
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous	S	T	R		
Property in Section	S	T	R		

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
6. IWM Job No. 29584

I, Allen H. McMachen, in a field survey on May, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1827 - John Mullet, D.S., Set quarter Section post, Wh. Oak 15" North 35 lks., Wh. Oak 10" S. 62° E., 12 lks.
1892 - D.J. Albertson, Stone & trace of U.S. stake OK by stumps of U.S. bearing trees. Set iron stake under stone, B.O. 2" S. 54° E. 12 lks., W.O. 24" S. 29½° E. 35 lks.
1946 - Wilkins & Wheaton, Ran North Section line & placed North quarter corner at bisection. Measured between Northwest corner and Northeast corner at 5316.23 feet. Also measured from stone at Center quarter corner North 2643.20 feet to North quarter corner.
1947 - Wilkins & Wheaton, Found 1946 measure from Center quarter corner to North quarter corner to be in error. Remeasured Center quarter corner to North quarter corner at 2652.35 feet. Also records plat of "Little Ranches" L. 16, Pg. 35 indicating measure of ±2653 feet between Center quarter corner and North quarter corner.
1960 - Acro Engineering, 28" Oak S. 80° E. 24.50', 18" Oak S. 85° E. 34.40', 10" Cherry N. 50° W. 24.50'.
1961-1979 - Gove Associates, Records plats: "Rollridge Acres" L. 27, Pg. 14, "Rollridge Acres No. 1", L. 27, Pg. 46 and "Rollridge Acres No. 2" L. 30, Pg. 07. (Projecting data from said plats indicates a measure of 2656.5 feet between North quarter corner and Northeast corner).
1972 - Ingersoll, Watson & McMachen, Measured from N¼ corner to Northeast corner @ 2656.53'.
1978 - Acro Engineering, Records plat of "Pine Knoll No. 1" L. 31, Pg. 47 & shows measure from C¼ corner North 1326.31' to 1/8 cor..
1989 - John Corbit, R.L.S., Records plat of "Highland Bluff" & shows measure from N¼ cor., West 2656.00' to NW corner.
1989 - Wilkins & Wheaton, Records plat of "Pine Knoll No. 2" L. 35, Pg. 10 indicating measure from Center quarter corner North 1326.31 feet to eighth corner and continuing North 1326.31 feet to North quarter corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ½" square iron rod. Found no previous accessories to corner. Removed found iron & dug 4' X 4' X 4' deep and found no further evidence of corner. Measured West 2656.23' to Harrison Monument at NW corner. Measured South 1326.15' to 1/8 corner.

**SURVEY &
REMONUMENTATION**

NOV 25 1998

SECTION

**RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
6-11-1998**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found ½" square iron is accepted as the best available evidence of the position of the original corner. Replaced found iron with a 30" Harrison Monument, Accessories:

60d nail in West face 12" Oak North 39.78'
60d nail in SW face 12" Oak N. 45° W. 30.28'
60d nail in North face 20" Oak S. 65° E. 36.53'
Found chiseled "X" on top of 28" X 20" stone S. 10° E. 10.40'



Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 10/22/98