



LC-000012
Page: 1 of 1
07/30/1999 08:24A
Bk-2 Pg-465

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Alamo Twp.

Kalamazoo
(County)

Located in:

Corner Code #

1. Public Land Survey T 1 S R 12 W G-10
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. _____ Recorded Plat _____
5. Private Claims

SURVEY &
REMONUMENTATION

FEB 08 2000

SECTION

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on May 21, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP 7-15-99

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1829: United States Government Surveyors, R. Clark; set 1/4 Section post.
White Oak 12" S. 12° E. 24 lks. White Oak 8" N. 45° W. 27 lks.
1907: E. Strong, County Surveyor; found U.S. stump N. 45° W. Stone graded out 8' deep. Set new stone 24" x 12" x 7".
White Oak 14" S. 50° W. 40 lks. Poplar 3" N. 45° W. 31 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1972: Gove Associates, County Witness Book; 1/2" iron.
12" Oak N. 70° W. 27.44' 24" Maple N. 45° E. 39.27'
18" Oak S. 50° E. 38.65'
1999: Found stone (24" x 12" x 7") with broken crockery 3 1/2' deep, below 1/2" x 18" iron in monument box. Iron was 0.42' North and 0.05' East of the position of the stone.
Noted: Nail/Tab in South Side Guard Rail Post N. 87° W. 17.21'
60d Nail in shoulder of road East 18.32'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-10: West 1/4 post, Section 27, T. 1 S., R. 12 W., ratified by the Kalamazoo County Remonumentation Program Peer Group on July 15, 1999 as a careful and faithful perpetuation of the position of the original corner. Found stone 24" x 12" x 7", 3 1/2 ft. below surface of road. Stone was set by E. Strong, County Surveyor in 1907 survey. Placed 20" Harrison monument in Monument box over the position of the stone.

Nail/Tab in South Side	24" Oak	N. 62° E.	39.51'
Nail/Tab in North Side	21" Double Oak	S. 52° E.	38.37'
60d Nail in South Side	16" Oak	S. 12° W.	76.10'
Nail/Tab in South Side	18" Triple Oak (center trunk)	N. 67° W.	27.50'

Signed by Robert E. Snell
Surveyor's Michigan License No. 9734

Date 7-28-99