

REMONUMENTATION

AUG 06 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo
(County)

Located In:

Corner Code #

Charleston Twp.

- | | | | | | |
|---|---|------|---|------|------|
| 1. Public Land Survey | T | 2 S. | R | 9 W. | C-11 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling
in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous
Property in Section | S | | T | R | |
| | S | | T | R | |

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, Robert E. Snell, in a field survey on April 23, 1996

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A 13x12 grid with columns labeled A through M and rows labeled 1 through 13. The grid contains numbers 1 through 36, arranged in a boustrophedon pattern (alternating rows from right to left and left to right). A black dot is located at the intersection of column C and row 12. Six arrows point outwards from this dot to the adjacent grid intersections: up, down, left, right, up-left, and down-left.

A. Description of original monument and accessories and/or subsequent restoration:

1826: United States Government Surveyors; set post common to Sections 29, 30, 31 & 32.

Wh. Oak 24" S. 10⁰ E. 29 lks.
Wh. Oak 18" N. 15⁰ E. 37 lks.

1883: F. Hodgman, County Surveyor; witnesses gone. Found old stake hold in center of road in line with fence West. Set 3' earthen post.

Elm 16"	N. $85\frac{1}{2}^0$	E.	$48\frac{1}{2}$ lks.
Maple 6"	S. $45\frac{1}{2}^0$	E.	$86\frac{1}{2}$ lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1974: Donald R. Gilchrist, R.L.S. #13583; found broken tile over good tile in monument box.

12" Hickory	N. 30° W.	68.51'
4" Oak	N. 35° E.	58.93'
4" Hickory	S. 40° E.	40.81'

1996: Found tile in monument box.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
5-16-1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-11: Southwest corner Section 29, T. 2 S., R. 9 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on May 16, 1996, and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile as set by F. Hodgman, County Surveyor in 1883 Remonumentation survey. Placed remonumentation sleeve over tile in monument box.

PK Nail on Northeasterly side of 10" Hickory	S. 25° E.	46.93'
PK Nail on North side of 12" Elm	N. 76° W.	26.04'
PK Nail on West side of 18" maple	N. 58° E.	34.17'
PK Nail on East side of 24" Shagbark Hickory	N. 20° W.	68.50'

Signed by

Date _____

Surveyor's Michigan License No.

9734

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983