

LAND CORNER RECORDATION CERTIFICATE,  
Filing Requirement of Act 74, Mich. P.A. 1970

94 APR 28 AM 9 12

For corners in

KALAMAZOO

(County)

Located In:

Corner Code #

Sec. 4, Charleston

1. Public Land Survey

T 2 S R 9 W

E-3

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

*Jared J. Jans*

CLERK-REGISTER

LIBER

1 PG 1147

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on February 7, 19 94,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1826-Original monument placed by U.S. Government Survey-Set Post to Sections 4, 5, 8 & 9.

Wh. Oak 10" South 39° East 49 Lks

Wh. Oak 6" North 55° West 62 Lks

1872-S. Hodgeman, County Surveyor-Stake at intersection of proportionate measurements from Quarter Post North, South, East, and West. All traces of original corner gone. Dug over a large surface thoroughly-Hullet promises to put in "T" Rail for corner-Nothing near for witness.

1883-F.Hodgeman, County Surveyor-Found "T" Rail 2' Long, set for corner on resurvey by S.C.Hodgeman. Nothing whatever by which to find original corner (see old record P.211-0). Sunk the "T" Rail 1' below surface & put 1' earthen post over with stone around.

Hickory 6" South 57° East 223½ Lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3" round tile with "X" and stone around with witness (1977)

8" Y. Pine East 12.94'

6" J. Pine North 45° East 25.8'

6" J. Pine North 65° East 28.5'

14" W. Cherry West 65.6'

**RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP**

3-3-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3 Southeast Corner Section 4, T. 2 S., R. 9 W., ratified by Kalamazoo County Remonumentation Program Peer Group on March 3, 1994. Found 3" round tile with "X" as called for in 1883 remonumentation survey by F.Hodgeman and is accepted as a careful and faithful perpetuation of the original corner's position. Placed remonumentation sleeve over tile.

PK Nail in Southeast Side 8" Jack Pine North 50° East 25.83'

PK Nail in North Side 11" Yellow Pine South 80° East 12.85'

(#25832) Nail/Tab in Southwest Side 6" Yellow Pine South 44° East 14.12'

(#25832) Nail/Tab in North Side 16" W. Cherry North 86° West 65.18'

Signed by

*Robert E. Snell*

Date

4-27-94

Surveyor's Michigan License No.

9734