SURVEY & REMONUMENTATION

| STATE OF | MICHIGAN |
|-----------|------------|
| COUNTY OF | KYLYMYYOO |
| PECFIVED | FOR RECORD |

| 1 | 1 |
|---|----|
| | 2- |

For corners in

APR 27 1995

LAND CORNER RECORDATION CERTIFICATE

| 2 | |
|---|--|
| | |

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970' 94 DEC 6 PM 3 55

| <u>K</u> | alamazoo (Caunty) | | Located In: | Corner Code ## | James Jump |
|----------|---|-------------|-------------------|----------------|---------------------------------------|
| | harleston Township Public Land Survey | , | T 2 S R 9 W | <u>G-1</u> | CLERK-REGISIER |
| 2. | | | T R T R T R | | LEER 1 PG1183 |
| 3. | in Section Miscellaneous Property in Sec. | s | T R T R T R | | Register of Deeds Stamp & File Number |
| | Lot No , Re | cordec | d Plat | | A B C D E F C H I J K L |


i, Robert E. Snell, in a field survey on February 28 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 11 12
- A. Description of original monument and accessories and/or subsequent restoration:
 - 1826 U.S. Government Survey-Intersected North Boundary 29 Lks West of Post. Set Post at intersection to corners Sections 3 and 4

48 Lks Wh. Oak $10^{\rm n}$ South 16° East 39° 75 Lks 14" South West Wh. Oak

- 1880 F. Hodgeman, County Surveyor-Destroyed. Set stake 29 Lks West of corresponding corner
- 1883 F. Hodgeman, County Surveyor-Set 3' earthen post 29 Lks West of corner of Section 33
- and 34, Ross
 Hickory 3" North 70° West 4 Lks
 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1994 Found capped iron just below surface. Dug down 12"-18" and found 3" round clay tile.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Northeast Corner Section 3, T. 2 S., R. 9 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on May 18, 1994. Found 3" round tile as called for in 1883 remonumentation survey by F. Hodgeman and is accepted as a careful and faithful perpetuation of the original corner's position. Placed remonumentation sleeve over tile and placed capped iron over.

Southeast Corner of House Foundation Southwest Corner of House Foundation North 10° West 31.50' E-W Fence South 11.8'

REVISED MAY 14, 1975 REVISED JAN., 1983

North 37° West 40.95'

PK Nail

PK Nail

in East Side 12" Maple North 60° West 12.73' in Northeast Corner RR TIe Fence Cor. South 68° East 30.44'

| Signed by Osfut 2 | Sould | Date 11-30-94 |
|--------------------------------|-------|--|
| Surveyor's Michigan License No | 9734 | FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 |