

SURVEY & REMONUMENTATION

OCT 06 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Charleston Twp.

Kalamazoo
(County)

Located in:

Corner Code #

- | | | |
|------------------------------------|-----------|------|
| 1. Public Land Survey | T 2S R 9W | K-13 |
| | T R | |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

CLERK - REGISTER

Handwritten signature

97 JUL 29 AM 11 00

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

LIBER 2 PAGE 153

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert E. Snell, in a field survey on May 21, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1825: United States Government Surveyor; set post, corner to Sections 35 & 36.

Wh. Oak 20"	N. 17° W.	145 lks.
Wh. Oak 14"	N. 85° W.	?

1883: F. Hodgman, County Surveyor; "Found stake and both U.S. bearing trees standing, bored 3 ft., filled the bottom with stone and put 2 ft. earthen post over. The U.S. Bearing Tree Wh. Oak 14" N. 85° W. is 110 lks. distant."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997: Found 3" round tile in East and West fence line about 3" above the surface. The top is badly deteriorated. Fence to South is East 5.73', tile K-1 Climax is East 5.73', Gov't. Jog = 9 lks. = 5.94'

Handwritten signature
**RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
6-19-1997**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13: Southeast corner, Section 35, T. 2 S., R. 9 W., ratified by the Kalamazoo County Remonumentation Program Peer Group on June 19, 1997 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round clay tile as set in 1883 Remonumentation Survey by F. Hodgman, County Surveyor, 3" above surface. Placed remonumentation sleeve over tile.

Exist. Nail/Tab in East Side	22" Oak	N. 32° W.	11.90'
Exist. Nail/Tab in East Side	12" W. Cherry	N. 32° E.	30.24'
PK Nail in South Side	8" W. Cherry	N. 78° E.	20.30'
PK Nail in North Side	12" W. Cherry	S. 62° E.	26.67'
Exist. Nail/Tab in South Side	8" Oak	N. 68° E.	20.45'

Signed by *Robert E. Snell*
Surveyor's Michigan License No. 9734

Date 7-29-97