

SURVEY & REMONUMENTATION

MAY 16 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

'96 APR 22 PM 4 23

For corners in
Kalamazoo
(County)
Kalamazoo Twp.

Located In:

Corner Code #

- | | | |
|------------------------------------|------------------------------|-------------|
| 1. Public Land Survey | T <u>2</u> S. R <u>11</u> W. | <u>B-05</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous | S _____ T _____ R _____ | _____ |
| Property in Section | S _____ T _____ R _____ | _____ |

James E. Young
CLERK-REGISTER

LIBER 1 PAGE 1474

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert E. Snell, in a field survey on March 8, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1827: United States Government Surveyors; set 1/4 Section post in prairie too much snow to raise mound.
- 1884: F. Hodgman, County Surveyor; found post removed and fence post standing in the corner. Bored (3 feet) down on the South side of the fence post and set 3 foot earthen post. Aspen 8" Dia. North 185½ lks. distant.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1944: Edw. J. Stevens, Reg. C.E.; found South 1/4 post Section 7 (same as N ¼ post Sec. 18).
- 1951: Edw. J. Stevens, Reg. C.E.; recorded plat "Westlawn" L-18, P-27 of plats.
- 1996: Found 3" round tile with "x" on top 20" below surface with ½" x 12" iron over.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP

4/18/96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- B-05: North ¼ post Section 18, T. 2 S., R. 11 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on April 18, 1996 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile with "x" on top as set by F. Hodgman, County Surveyor in a Remonumentation survey in 1885, down 20" with a ½" x 12" iron over the tile. Placed 20" Harrison monument over tile.

PK Nail in West Side	15" Wild Cherry	N. 10° E.	20.40'
PK Nail in North Side	8" Fir	S. 80° E.	12.89'
PK Nail in West Side	12" Fir	S. 15° E.	14.03'
PK Nail in North Side	26" Wild Cherry	N. 75° W.	23.62'

Signed by Robert E. Snell

Date 4-22-96

Surveyor's Michigan License No. 9734