

SURVEY &
REMONUMENTATION

APR 27 1995

LIBER

1 PG 1196

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

CLERK - REGISTER

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
94 DEC 9 AM 9 24

For corners in

Kalamazoo

(County)

Kalamazoo Township

Located In:

Corner Code #

1. Public Land Survey

T 2 S R 11 W

C-5

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on May 5, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1827: U.S. Government Survey; Set Post, Corner to Sections 7, 8, 17 and 18.

B. Oak 12" North $21\frac{1}{2}^{\circ}$ East 1468 Lks
B. Oak 10" North $02\frac{1}{2}^{\circ}$ West 1565 Lks

1863: F. Stimson, County Surveyor; Found stake by former survey and buried stone.

1884: F. Hodgeman, County Surveyor; Found stake, stone, old axe, and brick for corner and
bearings of resurvey correct. (Maple 6" N $86\frac{1}{2}^{\circ}$ W, 51 $\frac{1}{3}$ Lks, Maple 4" N $42\frac{1}{4}^{\circ}$ W,
76 $\frac{2}{3}$ Lks). Bored 3', filled bottom with brick and put 2' earthen post over with
stone around.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found 1/2" x 18" Pinch Pipe over tile in monument box.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
7-21-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-5 Southeast Corner Section 7, T. 2 S., R. 11 W., Ratified by the Kalamazoo County
Remonumentation Program Peer Group on July 21, 1994. Found 3" round tile as called
for by 1884 remonumentation survey by F. Hodgeman and is accepted as a careful and
faithful perpetuation of the original corner's position. Removed 1/2" x 18" Pinch Pipe
and monument box and replaced with 20" Harrison monument and new monument box over tile.

Existing Nail/Tab	North Side	Power Pole	N 65° E	27.72'
Chisled "X" in	East Rim	Sanitary Manhole Cover	S 54° W	35.22'
Existing Nail/Tab	South Side	Power Pole	N 68° W	30.77'
CL	Fire Hydrant		N 29° E	73.15'
	in CL Nichols Rd			

Signed by

Date

Surveyor's Michigan License No.

9734