ENTATION

For corners in

11995

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE LE HIGHMAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

'95 AUG 31 AM 11 24

KALAMAZOO (County)	Located In:	Corner Code #		•		,
KALAMAZOO TWP.				Sterne	a fre	ugol
Public Land Survey	T <u>2</u> R <u>11</u> T R T R			•	/ -REGIST	
Property Controlling in Section	S T R S T R		LIBER	1 113	340	
3. Miscellaneous Property in Section	S T R S T R		Register of De	eds Stamp &	k File Nun	nber
4. Lot No, F 5. Private Claims	Recorded Plat		2 6 3	C D F F	G H I .	J K L N
do hereby certify that under req in lines 1 and 2 above were in c manual of survey instructions Management or by a decree of 5 above were in conformance	juirements of P.A. 74, Michigan P.A. onformance with regulations and risk of the United States Department of Law and/or that the cowith the rules of the Michigan Bo	A. of 1970, the corner points mention rules therefore as required in the curr ment of the Interior, Bureau of La orner points mentioned in lines 3, 4 a pard of Professional Surveyors or b ted, re-monumented, recovered, for	ned 6 18 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	-8 - 9 - 17 - 16 17 - 16 17 - 16 17 - 17		4131213132413251
NOTE: Not more than 4 cor on this certificate.	mers, all in the same town and	range, may be recorded	11 12 31 13	32 33	343	5-36-
29 Corner post estal	blished by U.S. Deput	nd/or subsequent restoration: by Surveyor G. Risdon	"Int. N. bour	ndary of	twp. 66	lks.

182

1866 F. Stimson "Sec. cor. lost. Established by bisecting 2 miles on town line - stake & stone at corner- also stake and stone 2 rds. south".

1878 E. Strong (stone) Apple 4 SE. $40\frac{1}{2}$ Apple 4 SW. 49½

Date ? KCRC witness notes: Sidestone South 32.82' 12" Maple S30°W 30.24' WEL S60°W 92.56' 1977 Allen McMachen RLS 16935 LCRC Liber 1, Page 727 "1/2" pipe" See LCRC for witness info.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner and accessories not recovered.

Found 1 "X72" iron pipe directly over State of Michigan brass plate on post. State mon. is surrounded by stones. State mon. is stamped: "State of Michigan Section corner Sec.5 / Sec. 4 TIS R11W Unlawful to Move or Destroy This Marker"

Did not find stone 33' south. Road has been cut 4' -5' from natural ground.

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: El, Northeast corner Section 5, T2S, R11W, Ratified by kalamazoo County Remonumentation Peer Group on June 15, 1995 as a closing corner. State Monument location is accepted as the best available evidence of the position of the original corner. Set 20" Harrison Monument over State Monument in Mon. box.

Fnd. 3/4" rod in mon. box west 43.50'

Set P.K. nail in E. side 33" Maple S30°W 30.19'

Set P.K. nail in 22" Maple N30°E 38.87'

Top bolt on hydrant N56°W 51.59'

Surveyor's Michigan License No.__

Fnd. P.K. nail in P.P. N62°E 64.34° Fnd. 1/4" rod South 33.01

Signed by_

38116

Date 8-30-95

LAND SURVEYORS FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

HAHN

LAND SURVEYOR