



LC-000098
Page: 1 of 1
12/20/1999 10:07A
BK-2 Pg-551

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in CITY OF KALAMAZOO
KALAMAZOO
(County)

Located In: Corner Code #

1. Public Land Survey T 2S. R 11W. I-8
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

SURVEY &
REMONUMENTATION

FEB 08 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims
6. IWM Job No. 505

I, Allen H. McMachen, in a field survey on November 22 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4		3		2		1
3													
4	7			8			9		10		11		12
5													
6	18			17			16		15		14		13
7													
8	19			20			21		22		23		24
9													
10	30			29			28		27		26		25
11													
12	31			32			33		34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1827 - Robert Clark, Jr., Set ¼ Section post, W. Oak 12° N. 21° E. 26 lks., D.O. 10° S. 45° W. 14 lks.
June 1873 - Ed Strong, C.S. (V. 1, 290), "Square stone - in place of cedar stake by Stimson"
Oct. 1873 - Ed Strong, C.S. (V. 1, 290), "On Survey of West line of Sec. 23 by F. Hodgman and myself to ascertain whether the West ¼ was correctly placed. Found the center of said line 4' South of ¼ post by Stimson - but have not removed his post."
1880 - F. Hodgman, C.S. (V. 2, 400), "Lost. Bisected Section line very carefully and set post 24" X 6" X 6" four feet South of corner made by F. Stimson in 1863. Post 6" out of ground. See old record Page 290."
1957 - W.D. Ingersoll, R.L.S., Found stone 127.96' Northerly of North line Lake Street.
1985 - Ingersoll, Watson & McMachen, Inc., Found square marble stone in monument box 127.96 feet Northerly of North line of Lake Street.
1988 - I.W.M., Inc., Excavated for square marble stone but found it was removed during parking lot construction. Placed iron at 1957 position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No marker was recovered due to construction in the area. Placed a 30" Harrison Monument at previous position of the marble stone from survey markers still in place from the 1957 survey.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
12-9-1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Location of the Harrison Monument placed is accepted as a careful and faithful re-establishment of the position of the original corner. Placed monument box over Harrison Monument, Accessories:

- Mag nail in West side of U. Pole S. 12° E. 109.74'
Mag nail in Northwestern side of U. Pole N. 47° E. 34.41'
Northeast corner of bus garage N. 25° W. 25.52'
Southeast corner of bus garage S. 10° W. 67.41'



Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 12/17/99