

FEB 08 1999

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Climax Twp.

Kalamazoo  
(County)

Located In:

Corner Code #

1. Public Land Survey

T3S R9W  
T R  
T R  
T R

G-08

2. Property Controlling in Section

S T R  
S T R

3. Miscellaneous Property in Sec.

S T R  
S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert E. Snell, in a field survey on July 16, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

LIBER 2 PAGE 397

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD  
98 DEC 23 AM 9 15  
CLERK - REGISTER

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1826: United States Government Surveyors; set 1/4 Section post.

Beech 9" S. 53° W. 24 lks.  
Beech 12" N. 05° W. 24 lks.

1872: S. Hodgman, Deputy County Surveyor; "Stake, Government Witnesses Good."

1883: F. Hodgman, County Surveyor; "Found iron stake correct from stumps of 2 U.S. Bearing Trees. Set 3 ft. earthen post." Maple 24" S. 86° W. 28½ lks. Beech 16" S. 26½° E. 61 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Date Unknown: County Witness Book; tile at intersection of fence.

Maple 4" S. 45° W. 0.74' Oak 30" N. 50° W. 10.53' Maple 36" N. 05° E. 51.36'  
Dbl. Oak 60" N. 85° E. 37.04' Iron N. 03° W. 31.27'

Date Unknown: Wilkins & Wheaton Engr. Co.; witness notes, tile at intersection of fence  
12" Cherry N. 45° W. 10.25' 24" Triple Basswood N. 85° E. 36.75' 10" Oak  
N. 05° E. 51.3'

1997: Found top of "Mushroom Head" tile near surface on South bank of Drain. A piece of tile was found leaning to East. Further digging revealed tile with tree root over it. See 4" Maple above.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-08: East 1/4 post, Section 21, T. 3 S., R. 9 W., ratified by the Kalamazoo County Remonumentation Peer Group on August 21, 1997 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile with tree root growing over it. Tile was set in 1883 Remonumentation survey by F. Hodgman, County Surveyor. Placed 10" Harrison monument over tile.

PK Nail in North Side	12" Shagbark Hickory	East	24.52'
PK Nail in South Side	6" Ash	East	17.27'
PK Nail in North Side	6" Maple	S. 85° W.	9.75'
PK Nail in North Side	12" Maple	West	44.78'

Signed by

Robert E. Snell

Date

12-18-98

Surveyor's Michigan License No.

9734