

SURVEY &
REMONUMENTATION

APR 27 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo

(County)

Climax Township

Located In:

Corner Code ##

1. Public Land Survey

T 3 S R 9 W

J-7

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

CLERK - REGISTER

LIBER

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
94 DEC 30 AM 9 18

1 PG 1241

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on June 8, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1826: U.S. Government Survey; Set 1/4 Section Post.

Lynn 15" East 22 Lks
Beech 14" North 50° West 35 Lks

1864: F. Stimson, County Surveyor; Planted stake and stone.

1878: F. Hodgman, County Surveyor; Stone of former survey removed. From one witness tree,
set new stone (6" x 6" x 24") and noted,

Blk Walnut 6" North 52° West 84 Lks Blk Walnut 5" South 37½° East 111 Lks

1883: F. Hodgman, County Surveyor; Put a 1' earthen post underneath and restored the stone to

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: its' place.

1994: Found a large (6" x 6" x 24") rectangular stone over 1' of 3" round tile beneath.
Found an iron at 6.2' North and 0.9' East of tile.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
7-21-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-7 South 1/4 Post Section 14, T. 3 S., R. 9 W., Ratified by the Kalamazoo County Remonu-
mentation Program Peer Group on July 28, 1994. Found 3" round tile beneath stone as called
for in 1883 remonumentation survey by F. Hodgman and is accepted as a careful and faithful
perpetuation of the position of the original corner. Removed stone and placed a 30"
Harrison monument and monument box over tile.

Center Line "Q" Avenue North 1.5'
PK Nail in Northeast Side 23" Tulip South 55° East 51.93'
PK Nail in Northeast Side 31" Walnut South 30° East 69.40'
PK Nail in North Side 29" Maple South 60° West 61.07'
PK Nail in West Side 14" Hickory North 10° West 41.04'
Center Line 45th Street East 6.5'

Signed by

Date

Surveyor's Michigan License No.

9734