SURVEY & REMONUMENTATION

For comments in Citimax Kalamazoo Located in: Commer Code 8 1. Public Land Survey 1. Pu	7 FEB 2 6 1998	•
Located In: Corner Code # Company Controlling Company Controlling Controlling Company Controlling Controlling Company Controlling Controlling Company Controllin	SECTION LAND CORNER RECORDATION CERTIF For corners in C1 imax Filing Requirement of Act 74, Mich. P.A.	1070
1. Prublic Land Survey 1. 3 R. 9 N. K-10 1. R.	Kalamazoo	(= m 0 %
4. Lot No. 4. Lot No. 5. Private Claims Recorded Plat 5. Private Claims 1. Robert E. Snell 1. Robert B. Snell 1. Robert	1. Public Land Survey T 3S R 9W K-10 T R T R	7 17 E 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9
S. Private Claims 1. Robert E. Snell	In Section S T R	CIDER ZPAGE 246
Robert E. Snell na field survey on June 6 1977 on hereby state that under conformance with regularizers and nice therefore a regularizer to a first the corner ports are disconsistent of the state of the stat	4. Lot No, Recorded Plat	Register of Deeds Stamp & File Number
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this conflicate. A Description of original monument and accessories and/or subsequent restoration: 1826: United States Government Surveyors: Set & Section post Sugar 12" S. 760 W. 28 1ks. Sugar 8" S. 620 E. 27½ 1ks. 1833: F. Hodgman, County Surveyor: "Found stone of former survey, removed it and planted about two cubic yards sunk mostly below surface. Highest point of a liarge boulder containing The same boulder was former witness to corner but has been sunk since resurvey of 1869." B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. 1997: Found ½" x 18" iron with rocks around and a 3" x 4" piece of tile 6" below surface of the road. Tile piece laying on its side. Removed rocks and dug to 25" and found good section of tile. Noted railroad rail fence corners West 27.2' and N. 48° E., 39.4'. RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP AND REMONUMENTATION AND REMONUMENTATION AND REMONUMENTATION AND REMONUMENTATION AND REM	Robert E. Snell, in a field survey on June 6, 1997 do hereby state that under conformance with regulations and rules therefore as required in the current manual of survey instructions of the line of the interior, Bureau of Land Management or himself survey instructions of the	2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5 6 10 17 16 15 14 13
A Description of original monument and accessories and/or subsequent restoration: 1826: United States Government Surveyors: Set & Section post Sugar 12" S. 760 W. 28 lks. Sugar 8" S. 620 E. 27½ lks. 1883: F. Hodgman, County Surveyor: "Found stone of former survey, removed it and planted about two cubic yards sunk mostly below surface. Highest point of a large boulder containing The same boulder was former witness to corner but has been sunk since resurvey of 1869." B. Description of corner evidence found and/or method applied in testoring or reestablishing corner. 1997: Found ½" x 18" iron with rocks around and a 3" x 4" piece of tile 6" below surface of the road. Tile piece laying on its side. Removed rocks and dug to 25" and found good section of tile. Noted railroad rail fence corners West 27.2' and found N. 480 E., 39.4'. RATIFIED BY KALAMAZOO COUNTY K-10: West ½ post, 'Section 25, T. 3 S., R. 9 W., ratified by the kalamazoo County faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation Program Peer Group on August 21, 1997 and is accepted as a careful and below surface of road under ½" x 18" iron rod. Tile was set by F. Hodgman, County over tile with monument box. P.K. nail in North Side P.K. nail in North Side Outher Signed by Additional of the position of the county of the position of the county of		22 23 24
A Description of original monument and accessories and/or subsequent restoration: 1826: United States Government Surveyors: Set & Section post Sugar 12" S. 760 W. 28 lks. Sugar 8" S. 620 E. 27½ lks. 1883: F. Hodgman, County Surveyor: "Found stone of former survey, removed it and planted about two cubic yards sunk mostly below surface. Highest point of a large boulder containing The same boulder was former witness to corner but has been sunk since resurvey of 1869." B. Description of comer evidence found and/or method applied in restoring or reestablishing corner. 1997: Found ½" x 18" iron with rocks around and a 3" x 4" piece of tile 6" below surface of the road. Tile piece laying on its side. Removed rocks and dug to 25" and found good section of tile. Noted rail road rail fence corners West 27.2' and N. 48° E., 39.4'. RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP % 21-1497 K-10: West ½ post, Section 25, T. 3 S., R. 9 W., ratified by the Kalamazoo County faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation survey. Removed iron rod and set 20" Harrison monument box. P.K. nail in North Side P.K. nail in North Side P.K. nail in North Side Ash Signed by Signed by Surveyor in 1844.		10 30 29 28 27 26 25 11
Sugar 12" S. 760 W. 28 lks. Sugar 18" S. 620 E. 27½ lks. 1883: F. Hodgman, County Surveyor: "Found stone of former survey, removed it and planted about two cubic yards sunk mostly below surface. Highest point of a large boulder containing The same boulder was former witness to corner but has been sunk since resurvey of 1869." B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. 1997: Found ½" x 18" iron with rocks around and a 3" x 4" piece of tile 6" below surface of good section of tile. Noted railroad rail fence corners West 27, 2" and N. 48° E., 39.4'. RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 8-21-1497 K-10: West ½ post, Section 25, T. 3 S., R. 9 W., ratified by the Kalamazoo County faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation survey. Removed iron rod and set 20" Harrison monument box over tile with monument box. P.K. nail in North Side P.K. nail in North Side P.K. nail in North Side Ash S. 70° W. 28.90' N. 40° W. 34.40' Signed by Signed	A. Description of original monument and accessories and/or subsequent restoration:	13 35 36
Sugar 8" 5.760 W. 28 lks. Sugar 8" 5.60 E. 27½ lks. 1883: F. Hodgman, County Surveyor: "Found stone of former survey, removed it and planted about two cubic yards sunk mostly below surface. Highest point of a large boulder containing The same boulder was former witness to corner but has been sunk since resurvey of 1869." B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. 1997: Found ½" x 18" iron with rocks around and a 3" x 4" piece of tile 6" below surface of the road. Tile piece laying on its side. Removed rocks and dug to 25" and found good section of tile. Noted railroad rail fence corners West 27.2' and N. 48° E., 39.4'. RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP %-21-14q7 K-10: West ½ post, Section 25, T. 3 S., R. 9 W., ratified by the kalamazoo County faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation survey. Removed iron rod and set 20" Harrison monument box over tile with monument box. P.K. nail in North Side P.K. nail in North Side P.K. nail in North Side Ash S. 70° W. 28.90' N. 40° W. 34.40' Signed by Signed	Section nost	
3 ft. earthen post 4" below surface. Highest point of a large boulder containing The same boulder was former witness to corner but has been sunk since resurvey of 1869." B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. 1997: Found ½" x 18" iron with rocks around and a 3" x 4" piece of tile 6" below surface of good section of tile. Noted railroad rail fence corners West 27.2' and N. 48° E., 39.4'. RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP G-21-1497 K-10: West ½ post, Section 25, T. 3 S., R. 9 M., ratified by the Kalamazoo County faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation survey. Removed iron rod and set 20" Harrison monument box. P.K. nail in North Side Nail Malnut N. 40° W. 34.40°	Sugar 8" S. 520 F. 271 78.	
1997: Found ½" x 18" iron with rocks around and a 3" x 4" piece of tile 6" below surface of the road. Tile piece laying on its side. Removed rocks and dug to 25" and found good section of tile. Noted railroad rail fence corners West 27.2' and N. 48° E., 39.4'. RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP %-21-1497 K-10: West ¼ post, Section 25, T. 3 S., R. 9 W., ratified by the Kalamazoo County faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation survey. Removed iron rod and set 20" Harrison monument over tile with monument box. P.K. nail in North Side P.K. nail in North Side P.K. nail in North Side Ash S. 24° E. 54.89' P.K. nail in North Side Ash S. 700 W. 28.90' N. 400 W. 34.40' Signed by	3 ft. earthen post 4" below surface. Highest point of a about two cubic yards sunk mostly below surface is about The same boulder was former witness.	N. 500 E. 301 1 kg dial-
the road. Tile piece laying on its side. Removed rocks and dug to 25" and found good section of tile. Noted railroad rail fence corners West 27.2' and N. 48° E., 39.4'. RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP %-21-1497 K-10: West ½ post, Section 25, T. 3 S., R. 9 W., ratified by the Kalamazoo County faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation survey. Removed iron rod and set 20" Harrison monument p.K. nail in North Side Ash S. 24° E. 53.59' P.K. nail in North Side Ash S. 70° W. 28.90' N. 40° W. 34.40' Signed by Signed by	Description of corner evidence found and/or method applied in restoring or recetablishing and	since resurvey of 1869."
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-10: West ½ post, Section 25, T. 3 S., R. 9 W., ratified by the Kalamazoo County faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation survey. Removed iron rod and set 20" Harrison monument over tile with monument box. P.K. nail in North Side Ash S. 70° W. 28.90' N. 40° W. 34.40' Signed by	the road Tile piece It rocks around and a 3" x 4" piece	A of +:?. C" " -
faithful perpetuation of the position of the original corner. Found 3" round tile 25" Surveyor in 1883 Remonumentation survey. Removed iron rod and set 20" Harrison monument p.K. nail in North Side Nah S. 70° W. 28.90' Signed by	C. Description of manufacture	ALAMAZOO COUNTY MONUMENTATION PEER GROUP
P.K. nail in West Side Oak S. 24° E. 53.59' P.K. nail in North Side Ash S. 70° W. 28.90' N. 40° W. 34.40' Signed by Malnut N. 40° W. 34.40'	faithful perpetuation of the position of the original corbelow surface of road under ½" x 18" iron rod. Tile was over tile with monument box. P.K. nail in North Side	is accepted as a careful and ner. Found 3" round tile 25" set by F. Hodgman, County d and set 20" Harrison monument
Signed by	P.K. nail in West Side Oak S. 240 P.K. nail in North Side Ash S. 700	E. 54.89'
Surveyor's Michigan License No. 9734 Date 12-16-97	Signed by West 2. And	W. 34.40
	Surveyor's Michigan License No. 9734 Date 12.	16-97