

SURVEY &
REMONUMENTATION

FEB 26 1998

1-
2- SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Climax Township

Kalamazoo
(County)

Located In:

Corner Code #

1. Public Land Survey

T 3S R 9W

L-13

2. Property Controlling
in Section

S
S

T
T

3. Miscellaneous
Property in Sec.

S
S

T
T

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert E. Snell, in a field survey on August 4, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1825: United States Government Surveyors: Set $\frac{1}{4}$ Section Post.
Lynn 6" N. 65° E. 27 lks.
White Ash 7" N. 40° W. 19 lks.

1883: F. Hodgman, County Surveyor: "Post and witnesses gone. A large stone set by R. Nutting for the North $\frac{1}{4}$ post of Section 1, Wakeshma stands in the North edge of crossway. This I found correct in a previous survey of Section 1. Measured 10 links West from this stone and set 3 ft. of earthen post in swamp hole."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997: Found tile down about 24" on West edge of crossway (road fill) top section has been removed. A piece of tile was found 4' Southwest of this point. The second section was O.K. in a layer of grey marl. Placed $1\frac{1}{2}$ " pipe North 0.42' and noted centerline of Northwest end of culvert S. 10° E., 13.22'.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
8-21-1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-13: South $\frac{1}{2}$ Post, Section 36, T. 3 S., R. 9 W.; Ratified by the Kalamazoo County Remonumentation Program Peer Group on August 21, 1997 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile 24" below surface of road fill. Tile set by F. Hodgman, county surveyor in a 1883 remonumentation survey. Placed a 20" Harrison monument over tile. Wakeshma corner is East 6.65'.

P.K. nail in West side	Wooden Fence Post	N. 16° E.	27.59'
P.K. nail in South side	14" Elm	N. 50° E.	9.85'
Centerline West Leg	Arrow Sign	N. 80° E.	2.85'
P.K. nail in East side	6" Walnut	S. 25° W.	40.66'

Signed by Robert E. Snell
Surveyor's Michigan License No. 9734

Date 12-16-97