

OCT 06 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo (County)  
Pavilion Township  
1. Public Land Survey Located In: T 3S R 10W Corner Code # C-9  
2. Property Controlling in Section S T R  
3. Miscellaneous Property in Sec. S T R

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD  
97 AUG 25 AM 11 57  
CLERK - REGISTER  
LIBER 2 PAGE 191

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Thomas W. Chettleburgh, in a field survey on July 25, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Wilkins & Wheaton, 1941, Found tile  
John Stack, 1960, Found tile  
Ingersoll, Watson, McMachen, Found tile, set iron bar 33.00' West.  
Wilkins & Wheaton, 1990's, tile missing, set iron bar from 1942 witnesses and iron bar 33.00' West.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron bar at corner, checks 1942 witnesses  
Found iron bar 33.00' West  
The found iron bar was ratified by the Kalamazoo County Remonumentation Program Peer Group on July 16, 1997 and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced iron bar with 30" Harrison Monument  
Spike N. side 21" Oak S76°E 43.87'  
Spike SW-side 18" Oak S24°E 23.16'  
Spike W side 15" Hickory S17°E 32.24'  
Spike NW side 11" Hickory S30°W 7.48'  
Spike N. side 12" Oak S87°W 19.80'



Signed by Thomas W. Chettleburgh  
Surveyor's Michigan License No. 16036

Date July 28, 1997